



Miller®

OM-495

192 774AR

October 2003

Processes



Stick (SMAW) Welding



TIG (GTAW) Welding



MIG (GMAW) Welding



Flux Cored (FCAW) Welding




Air Carbon Arc (CAC-A)
Cutting and Gouging

Description



Engine Driven Welding Generator

Big Blue® 402D, 502D, 602D



CE And Non-CE Models



Visit our website at
www.MillerWelds.com

OWNER'S MANUAL

From Miller to You

Thank you and congratulations on choosing Miller. Now you can get the job done and get it done right. We know you don't have time to do it any other way.

That's why when Niels Miller first started building arc welders in 1929, he made sure his products offered long-lasting value and superior quality. Like you, his customers couldn't afford anything less. Miller products had to be more than the best they could be. They had to be the best you could buy.

Today, the people that build and sell Miller products continue the tradition. They're just as committed to providing equipment and service that meets the high standards of quality and value established in 1929.

This Owner's Manual is designed to help you get the most out of your Miller products. Please take time to read the Safety precautions. They will help you protect yourself against potential hazards on the worksite.

We've made installation and operation quick and easy. With Miller you can count on years of reliable service with proper maintenance. And if for some reason the unit needs repair, there's a Troubleshooting section that will help you figure out what the problem is. The parts list will then help you to decide the exact part you may need to fix the problem. Warranty and service information for your particular model are also provided.



Miller is the first welding equipment manufacturer in the U.S.A. to be registered to the ISO 9001:2000 Quality System Standard.



Miller Electric manufactures a full line of welders and welding related equipment.

For information on other quality Miller products, contact your local Miller distributor to receive the latest full line catalog or individual catalog sheets. **To locate your nearest distributor or service agency call 1-800-4-A-Miller, or visit us at www.MillerWelds.com on the web.**



Working as hard as you do – every power source from Miller is backed by the most hassle-free warranty in the business.

TABLE OF CONTENTS

SECTION 1 – SAFETY PRECAUTIONS – READ BEFORE USING	1
1-1. Symbol Usage	1
1-2. Arc Welding Hazards	1
1-3. Engine Hazards	2
1-4. Compressed Air Hazards	3
1-5. Additional Symbols For Installation, Operation, And Maintenance	3
1-6. California Proposition 65 Warnings	4
1-7. Principal Safety Standards	4
1-8. EMF Information	4
SECTION 2 – CONSIGNES DE SÉCURITÉ – LIRE AVANT UTILISATION	5
2-1. Signification des symboles	5
2-2. Dangers relatifs au soudage à l'arc	5
2-3. Dangers existant en relation avec le moteur	6
2-4. Dangers liés à l'air comprimé	7
2-5. Dangers supplémentaires en relation avec l'installation, le fonctionnement et la maintenance	7
2-6. Principales normes de sécurité	8
2-7. Information sur les champs électromagnétiques	8
SECTION 3 – DEFINITIONS	9
3-1. Warning Label Definitions (For Wordless Labels)	9
3-2. Manufacturer's Rating Labels For Non-CE Products	13
3-3. Manufacturer's Rating Labels For CE Products	14
3-4. Symbols And Definitions	15
SECTION 4 – SPECIFICATIONS	16
4-1. Weld, Power, And Engine Specifications	16
4-2. Dimensions, Weights, And Operating Angles	16
4-3. Volt-Ampere Curves For CC Models	17
4-4. Volt-Ampere Curves For CC/CV Models	18
4-5. Fuel Consumption	19
4-6. Duty Cycle And Overheating	20
4-7. AC Generator Power Curve	21
4-8. Optional Three-Phase Generator Curves	22
SECTION 5 – INSTALLATION	24
5-1. Installing Welding Generator (See Sections 5-2 And 5-3)	24
5-2. Using Lifting Eye	25
5-3. Mounting Welding Generator	26
5-4. Installing Exhaust Pipe	27
5-5. Installing Engine Side Baffle (CE Models Only)	27
5-6. Activating The Dry Charge Battery (If Applicable)	28
5-7. Connecting The Battery	29
5-8. Installing Optional Ether Cylinder (Deutz F3L912 Engine Only)	29
5-9. Engine Prestart Checks	30
5-10. Connecting To Weld Output Terminals	31
5-11. Selecting Weld Cable Sizes*	31
5-12. Connecting To Remote Amperage Adjust Receptacle RC13 On CC Models	32
5-13. Connecting To Remote 14 Receptacle RC14 On CC/CV Models	32
SECTION 6 – OPERATING WELDING GENERATOR – CC MODELS	34
6-1. Front Panel Controls For CC Models (See Section 6-2)	34
6-2. Description Of Front Panel Controls For CC Models (See Section 6-1)	35
6-3. Remote Amperage Control On CC Models (Optional)	36
6-4. Weld Control/Arc Condition Information Label	36

TABLE OF CONTENTS

SECTION 7 – OPERATING WELDING GENERATOR – CC/CV MODELS	38
7-1. Front Panel Controls For CC/CV Models (See Section 7-2)	38
7-2. Description Of Front Panel Controls For CC/CV Models (See Section 7-1)	39
7-3. Process/Contactor Switch On CC/CV Models	40
7-4. Remote Voltage/Ampereage Control On CC/CV Models (Optional)	41
SECTION 8 – OPERATING AUXILIARY EQUIPMENT	42
8-1. Generator Power Receptacles (Standard Models)	42
8-2. Connecting To Optional Three-Phase Generator (CC/CV Standard Models Only)	43
8-3. Optional Generator Power Receptacles (Standard Models)	44
8-4. Generator Power Receptacles (CE Models)	45
SECTION 9 – MAINTENANCE (DEUTZ F4L2011-POWERED UNITS).....	46
9-1. Routine Maintenance (Deutz F4L2011-Powered Units)	46
9-2. Maintenance Label	48
9-3. Servicing Air Cleaner (Deutz F4L2011-Powered Units)	49
9-4. Inspecting/Cleaning Optional Spark Arrestor (Deutz F4L2011-Powered Units)	50
9-5. Adjusting Engine Speed (Deutz F4L2011-Powered Units)	51
9-6. Servicing Fuel And Lubrication Systems (Deutz F4L2011-Powered Units)	52
9-7. Overload Protection (Deutz F4L2011-Powered Units)	53
SECTION 10 – MAINTENANCE (DEUTZ F3L912-POWERED UNITS)	54
10-1. Routine Maintenance (Deutz F3L912-Powered Units)	54
10-2. Maintenance Label	56
10-3. Servicing Air Cleaner (Deutz F3L912-Powered Units)	57
10-4. Inspecting/Cleaning Optional Spark Arrestor (Deutz F3L912-Powered Units)	58
10-5. Adjusting Engine Speed (Deutz F3L912-Powered Units)	59
10-6. Servicing Optional Ether Starting Aid (Deutz F3L912-Powered Units)	59
10-7. Servicing Fuel And Lubrication Systems (Deutz F3L912-Powered Units)	60
10-8. Overload Protection (Deutz F3L912-Powered Units)	61
SECTION 11 – TROUBLESHOOTING	62
11-1. Diagnosing Causes Of Engine Fault Shutdowns	62
11-2. Troubleshooting Tables	63
SECTION 12 – ELECTRICAL DIAGRAMS	68
SECTION 13 – RUN-IN PROCEDURE	80
13-1. Wetstacking	80
13-2. Run-In Procedure Using Load Bank	81
13-3. Run-In Procedure Using Resistance Grid	82
SECTION 14 – GENERATOR POWER GUIDELINES	83
SECTION 15 – PARTS LIST	90
OPTIONS AND ACCESSORIES	
WARRANTY	

Declaration of Conformity for European Community (CE) Products

NOTE



This information is provided for units with CE certification (see rating label on unit).

Manufacturer's Name:

Miller Electric Mfg. Co.

Manufacturer's Address:

1635 W. Spencer Street
Appleton, WI 54914 USA

Declares that the product:

Big Blue® 602D (Deutz F4L1011-Powered Models)

conforms to the following Directives and Standards:

Directives

Low Voltage Directive: 73/23/EEC

Machinery Directives: 98/37/EEC, 91/368/EEC, 93/C 133/04, 93/68/EEC

Noise level of Welding Generators: 2000/14/EC

Electromagnetic compatibility Directives: 89/336/EEC, 92/31/EEC

Standards

Safety Requirements for Arc Welding Equipment IEC 60974-1: 1998-09

Rotating Electrical Machines – Part 1: Rating and Performance: IEC 34-1: 1994

Rotating Electrical Machines – Part 5: Classification of degrees of protection provided by enclosure of rotating electrical machines (IP code): IEC 34-5: 1991

Insulation coordination for equipment within low-voltage systems:
Part 1: Principles, requirements and test: IEC 60664-1: 2000-04

Electromagnetic compatibility (EMC) Product standard for arc welding equipment: EN50199: August 1995

European Contact:

Mr. Danilo Fedolfi, Managing Director
ITW WELDING PRODUCTS ITALY S.r.l.
Via Privata Iseo 6/E
20098 San Giuliano
Milanese, Italy

Telephone:

39(02)98290-1

Fax:

39(02)98290-203

Declaration of Conformity for European Community (CE) Products

NOTE



This information is provided for units with CE certification (see rating label on unit).

Manufacturer's Name:

Miller Electric Mfg. Co.

Manufacturer's Address:

1635 W. Spencer Street
Appleton, WI 54914 USA

Declares that the product:

Big Blue® 602D (Deutz F4L1011-Powered Models)

conforms to the following Directives and Standards relating to sound levels:

Directives

Noise Level Of Welding Generators: 2000/14/EC

Sound Level Information

Measured Sound Power Level: 98 dB

Guaranteed Sound Power Level: 98 dB

This equipment conforms to requirements brought forth by 2000/14/EC

Noise conformity assessment procedure followed with notified body:

AV Technology Limited
AVTECH House
Birdhall Lane
Cheadle Heath
Stockport
Cheshire
SK3OXU

Sound power level requirements determined by the 40% duty cycle of 600 A, 30 V

Conforming assessment procedure 1 of Annex VI will be followed.

European Contact:

Mr. Danilo Fedolfi, Managing Director
MILLER Europe S.r.l.
Via Privata Iseo 6/E
20098 San Giuliano
Milanese, Italy

Telephone:

39(02)98290-1

Fax:

39(02)98290203

SECTION 1 – SAFETY PRECAUTIONS – READ BEFORE USING

rom_nd_10/02

▲ Warning: Protect yourself and others from injury — read and follow these precautions.

1-1. Symbol Usage



Means Warning! Watch Out! There are possible hazards with this procedure! The possible hazards are shown in the adjoining symbols.



▲ Marks a special safety message.

☞ Means "Note"; not safety related.

1-2. Arc Welding Hazards

▲ The symbols shown below are used throughout this manual to call attention to and identify possible hazards. When you see the symbol, watch out, and follow the related instructions to avoid the hazard. The safety information given below is only a summary of the more complete safety information found in the Safety Standards listed in Section 1-7. Read and follow all Safety Standards.

▲ Only qualified persons should install, operate, maintain, and repair this unit.

▲ During operation, keep everybody, especially children, away.



ELECTRIC SHOCK can kill.

Touching live electrical parts can cause fatal shocks or severe burns. The electrode and work circuit is electrically live whenever the output is on. The input power circuit and machine internal circuits are also live when power is on. In semiautomatic or automatic wire welding, the wire, wire reel, drive roll housing, and all metal parts touching the welding wire are electrically live. Incorrectly installed or improperly grounded equipment is a hazard.

- Do not touch live electrical parts.
- Wear dry, hole-free insulating gloves and body protection.
- Insulate yourself from work and ground using dry insulating mats or covers big enough to prevent any physical contact with the work or ground.
- Do not use AC output in damp areas, if movement is confined, or if there is a danger of falling.
- Use AC output ONLY if required for the welding process.
- If AC output is required, use remote output control if present on unit.
- Additional safety precautions are required when any of the following electrically hazardous conditions are present: in damp locations or while wearing wet clothing; on metal structures such as floors, gratings, or scaffolds; when in cramped positions such as sitting, kneeling, or lying; or when there is a high risk of unavoidable or accidental contact with the workpiece or ground. For these conditions, use the following equipment in order presented: 1) a semiautomatic DC constant voltage (wire) welder, 2) a DC manual (stick) welder, or 3) an AC welder with reduced open-circuit voltage. In most situations, use of a DC, constant voltage wire welder is recommended. And, do not work alone!
- Disconnect input power or stop engine before installing or servicing this equipment. Lockout/tagout input power according to OSHA 29 CFR 1910.147 (see Safety Standards).
- Properly install and ground this equipment according to its Owner's Manual and national, state, and local codes.
- Always verify the supply ground — check and be sure that input power cord ground wire is properly connected to ground terminal in disconnect box or that cord plug is connected to a properly grounded receptacle outlet.
- When making input connections, attach proper grounding conductor first — double-check connections.
- Frequently inspect input power cord for damage or bare wiring — replace cord immediately if damaged — bare wiring can kill.
- Turn off all equipment when not in use.
- Do not use worn, damaged, undersized, or poorly spliced cables.
- Do not drape cables over your body.
- If earth grounding of the workpiece is required, ground it directly with a separate cable.
- Do not touch electrode if you are in contact with the work, ground, or another electrode from a different machine.

- Use only well-maintained equipment. Repair or replace damaged parts at once. Maintain unit according to manual.
- Wear a safety harness if working above floor level.
- Keep all panels and covers securely in place.
- Clamp work cable with good metal-to-metal contact to workpiece or work-table as near the weld as practical.
- Insulate work clamp when not connected to workpiece to prevent contact with any metal object.
- Do not connect more than one electrode or work cable to any single weld output terminal.

SIGNIFICANT DC VOLTAGE exists in inverters after stopping engine.

- Stop engine on inverter and discharge input capacitors according to instructions in Maintenance Section before touching any parts.



FUMES AND GASES can be hazardous.

Welding produces fumes and gases. Breathing these fumes and gases can be hazardous to your health.

- Keep your head out of the fumes. Do not breathe the fumes.
- If inside, ventilate the area and/or use exhaust at the arc to remove welding fumes and gases.
- If ventilation is poor, use an approved air-supplied respirator.
- Read the Material Safety Data Sheets (MSDSs) and the manufacturer's instructions for metals, consumables, coatings, cleaners, and degreasers.
- Work in a confined space only if it is well ventilated, or while wearing an air-supplied respirator. Always have a trained watchperson nearby. Welding fumes and gases can displace air and lower the oxygen level causing injury or death. Be sure the breathing air is safe.
- Do not weld in locations near degreasing, cleaning, or spraying operations. The heat and rays of the arc can react with vapors to form highly toxic and irritating gases.
- Do not weld on coated metals, such as galvanized, lead, or cadmium plated steel, unless the coating is removed from the weld area, the area is well ventilated, and if necessary, while wearing an air-supplied respirator. The coatings and any metals containing these elements can give off toxic fumes if welded.



BUILDDUP OF GAS can injure or kill.

- Shut off shielding gas supply when not in use.
- Always ventilate confined spaces or use approved air-supplied respirator.



ARC RAYS can burn eyes and skin.

Arc rays from the welding process produce intense visible and invisible (ultraviolet and infrared) rays that can burn eyes and skin. Sparks fly off from the weld.


- Wear a welding helmet fitted with a proper shade of filter to protect your face and eyes from arc rays and sparks when welding or watching (see ANSI Z49.1 and Z87.1 listed in Safety Standards).
- Wear approved safety glasses with side shields under your helmet.
- Use protective screens or barriers to protect others from flash and glare; warn others not to watch the arc.
- Wear protective clothing made from durable, flame-resistant material (wool and leather) and foot protection.



WELDING can cause fire or explosion.

Welding on closed containers, such as tanks, drums, or pipes, can cause them to blow up. Sparks can fly off from the welding arc. The flying sparks, hot workpiece, and hot equipment can cause fires and burns. Accidental contact of electrode to metal objects can cause sparks, explosion, overheating, or fire. Check and be sure the area is safe before doing any welding.

- Protect yourself and others from flying sparks and hot metal.
- Do not weld where flying sparks can strike flammable material.
- Remove all flammables within 35 ft (10.7 m) of the welding arc. If this is not possible, tightly cover them with approved covers.
- Be alert that welding sparks and hot materials from welding can easily go through small cracks and openings to adjacent areas.
- Watch for fire, and keep a fire extinguisher nearby.
- Be aware that welding on a ceiling, floor, bulkhead, or partition can cause fire on the hidden side.
- Do not weld on closed containers such as tanks, drums, or pipes, unless they are properly prepared according to AWS F4.1 (see Safety Standards).
- Connect work cable to the work as close to the welding area as practical to prevent welding current from traveling long, possibly unknown paths and causing electric shock and fire hazards.
- Do not use welder to thaw frozen pipes.
- Remove stick electrode from holder or cut off welding wire at contact tip when not in use.
- Wear oil-free protective garments such as leather gloves, heavy shirt, cuffless trousers, high shoes, and a cap.
- Remove any combustibles, such as a butane lighter or matches, from your person before doing any welding.
- Follow requirements in OSHA 1910.252 (a) (2) (iv) and NFPA 51B for hot work and have a fire watcher and extinguisher nearby.



FLYING METAL can injure eyes.

- Welding, chipping, wire brushing, and grinding cause sparks and flying metal. As welds cool, they can throw off slag.
- Wear approved safety glasses with side shields even under your welding helmet.



HOT PARTS can cause severe burns.

- Allow cooling period before maintaining.
- Wear protective gloves and clothing when working on a hot engine.
- Do not touch hot engine parts or just-welded parts bare-handed.



NOISE can damage hearing.

Noise from some processes or equipment can damage hearing.

- Wear approved ear protection if noise level is high.



MAGNETIC FIELDS can affect pacemakers.

- Pacemaker wearers keep away.
- Wearers should consult their doctor before going near arc welding, gouging, or spot welding operations.



CYLINDERS can explode if damaged.

Shielding gas cylinders contain gas under high pressure. If damaged, a cylinder can explode. Since gas cylinders are normally part of the welding process, be sure to treat them carefully.

- Protect compressed gas cylinders from excessive heat, mechanical shocks, slag, open flames, sparks, and arcs.
- Install cylinders in an upright position by securing to a stationary support or cylinder rack to prevent falling or tipping.
- Keep cylinders away from any welding or other electrical circuits.
- Never drape a welding torch over a gas cylinder.
- Never allow a welding electrode to touch any cylinder.
- Never weld on a pressurized cylinder — explosion will result.
- Use only correct shielding gas cylinders, regulators, hoses, and fittings designed for the specific application; maintain them and associated parts in good condition.
- Turn face away from valve outlet when opening cylinder valve.
- Keep protective cap in place over valve except when cylinder is in use or connected for use.
- Read and follow instructions on compressed gas cylinders, associated equipment, and CGA publication P-1 listed in Safety Standards.

1-3. Engine Hazards



BATTERY EXPLOSION can BLIND.

- Always wear a face shield, rubber gloves, and protective clothing when working on a battery.
- Stop engine before disconnecting or connecting battery cables or servicing battery.
- Do not allow tools to cause sparks when working on a battery.
- Do not use welder to charge batteries or jump start vehicles.
- Observe correct polarity (+ and -) on batteries.
- Disconnect negative (-) cable first and connect it last.



FUEL can cause fire or explosion.

- Stop engine and let it cool off before checking or adding fuel.
- Do not add fuel while smoking or if unit is near any sparks or open flames.
- Do not overfill tank — allow room for fuel to expand.
- Do not spill fuel. If fuel is spilled, clean up before starting engine.
- Dispose of rags in a fireproof container.
- Always keep nozzle in contact with tank when fueling.



MOVING PARTS can cause injury.

- Keep away from fans, belts, and rotors.
- Keep all doors, panels, covers, and guards closed and securely in place.
- Stop engine before installing or connecting unit.
- Have only qualified people remove guards or covers for maintenance and troubleshooting as necessary.
- To prevent accidental starting during servicing, disconnect negative (-) battery cable from battery.
- Keep hands, hair, loose clothing, and tools away from moving parts.
- Reinstall panels or guards and close doors when servicing is finished and before starting engine.
- Before working on generator, remove spark plugs or injectors to keep engine from kicking back or starting.
- Block flywheel so that it will not turn while working on generator components.



STEAM AND HOT COOLANT can burn.

- If possible, check coolant level when engine is cold to avoid scalding.
- Always check coolant level at overflow tank, if present on unit, instead of radiator (unless told otherwise in maintenance section or engine manual).
- If the engine is warm, checking is needed, and there is no overflow tank, follow the next two statements.
- Wear safety glasses and gloves and put a rag over radiator cap.
- Turn cap slightly and let pressure escape slowly before completely removing cap.



BATTERY ACID can BURN SKIN and EYES.

- Do not tip battery.
- Replace damaged battery.
- Flush eyes and skin immediately with water.



ENGINE HEAT can cause fire.

- Do not locate unit on, over, or near combustible surfaces or flammables.
- Keep exhaust and exhaust pipes way from flammables.



ENGINE EXHAUST GASES can kill.

- Use equipment outside in open, well-ventilated areas.
- If used in a closed area, vent engine exhaust outside and away from any building air intakes.



EXHAUST SPARKS can cause fire.

- Do not let engine exhaust sparks cause fire.
- Use approved engine exhaust spark arrestor in required areas — see applicable codes.

1-4. Compressed Air Hazards




BREATHING COMPRESSED AIR can cause serious injury or death.

- Do not use compressed air for breathing.
- Use only for cutting, gouging, and tools.



HOT METAL from air arc cutting and gouging can cause fire or explosion.

- Do not cut or gouge near flammables.
- Watch for fire; keep extinguisher nearby.




COMPRESSED AIR can cause injury.

- Wear approved safety goggles.
- Do not direct air stream toward self or others.




HOT PARTS can cause burns and injury.

- Do not touch hot compressor or air system parts.
- Let system cool down before touching or servicing.



TRAPPED AIR PRESSURE AND WHIPPING HOSES can cause injury.

- Release air pressure from tools and system before servicing, adding or changing attachments, or opening compressor oil drain or oil fill cap.



READ INSTRUCTIONS.


- Read Owner's Manual before using or servicing unit.
- Stop engine and release air pressure before servicing.

1-5. Additional Symbols For Installation, Operation, And Maintenance




FALLING UNIT can cause injury.

- Use lifting eye to lift unit only, NOT running gear, gas cylinders, trailer, or any other accessories.
- Use equipment of adequate capacity to lift and support unit.
- If using lift forks to move unit, be sure forks are long enough to extend beyond opposite side of unit.



OVERUSE can cause OVERHEATING.

- Allow cooling period; follow rated duty cycle.
- Reduce current or reduce duty cycle before starting to weld again.
- Do not block or filter airflow to unit.




OVERHEATING can damage motors.

- Turn off or unplug equipment before starting or stopping engine.
- Do not let low voltage and frequency caused by low engine speed damage electric motors.
- Do not connect 50 or 60 Hertz motors to the 100 Hertz receptacle where applicable.




STATIC (ESD) can damage PC boards.

- Put on grounded wrist strap BEFORE handling boards or parts.
- Use proper static-proof bags and boxes to store, move, or ship PC boards.




FLYING SPARKS can cause injury.

- Wear a face shield to protect eyes and face.
- Shape tungsten electrode only on grinder with proper guards in a safe location wearing proper face, hand, and body protection.
- Sparks can cause fires — keep flammables away.




TILTING OF TRAILER can cause injury.

- Use tongue jack or blocks to support weight.
- Properly install welding generator onto trailer according to instructions supplied with trailer.




READ INSTRUCTIONS.

- Use only genuine MILLER/Hobart replacement parts.
- Perform engine and air compressor (if applicable) maintenance and service according to this manual and the engine/air compressor (if applicable) manuals.



H.F. RADIATION can cause interference.

- High-frequency (H.F.) can interfere with radio navigation, safety services, computers, and communications equipment.
- Have only qualified persons familiar with electronic equipment perform this installation.
- The user is responsible for having a qualified electrician promptly correct any interference problem resulting from the installation.
- If notified by the FCC about interference, stop using the equipment at once.
- Have the installation regularly checked and maintained.
- Keep high-frequency source doors and panels tightly shut, keep spark gaps at correct setting, and use grounding and shielding to minimize the possibility of interference.



ARC WELDING can cause interference.

- Electromagnetic energy can interfere with sensitive electronic equipment such as microprocessors, computers, and computer-driven equipment such as robots.
- Be sure all equipment in the welding area is electromagnetically compatible.

- To reduce possible interference, keep weld cables as short as possible, close together, and down low, such as on the floor.
- Locate welding operation 100 meters from any sensitive electronic equipment.
- Be sure this welding machine is installed and grounded according to this manual.
- If interference still occurs, the user must take extra measures such as moving the welding machine, using shielded cables, using line filters, or shielding the work area.

1-6. California Proposition 65 Warnings

- ▲ Welding or cutting equipment produces fumes or gases which contain chemicals known to the State of California to cause birth defects and, in some cases, cancer. (California Health & Safety Code Section 25249.5 et seq.)
- ▲ Battery posts, terminals and related accessories contain lead and lead compounds, chemicals known to the State of California to cause cancer and birth defects or other reproductive harm. Wash hands after handling.

For Gasoline Engines:

- ▲ Engine exhaust contains chemicals known to the State of California to cause cancer, birth defects, or other reproductive harm.

For Diesel Engines:

- ▲ Diesel engine exhaust and some of its constituents are known to the State of California to cause cancer, birth defects, and other reproductive harm.

1-7. Principal Safety Standards

Safety in Welding, Cutting, and Allied Processes, ANSI Standard Z49.1, from American Welding Society, 550 N.W. LeJeune Rd, Miami FL 33126 (phone: 305-443-9353, website: www.aws.org).

Recommended Safe Practices for the Preparation for Welding and Cutting of Containers and Piping, American Welding Society Standard AWS F4.1, from American Welding Society, 550 N.W. LeJeune Rd, Miami, FL 33126 (phone: 305-443-9353, website: www.aws.org).

National Electrical Code, NFPA Standard 70, from National Fire Protection Association, P.O. Box 9101, 1 Battery March Park, Quincy, MA 02269-9101 (phone: 617-770-3000, website: www.nfpa.org and www.sparky.org).

Safe Handling of Compressed Gases in Cylinders, CGA Pamphlet P-1, from Compressed Gas Association, 1735 Jefferson Davis Highway, Suite 1004, Arlington, VA 22202-4102 (phone: 703-412-0900, website: www.cganet.com).

Code for Safety in Welding and Cutting, CSA Standard W117.2, from Canadian Standards Association, Standards Sales, 178 Rexdale Bou-

levard, Rexdale, Ontario, Canada M9W 1R3 (phone: 800-463-6727 or in Toronto 416-747-4044, website: www.csa-international.org).

Practice For Occupational And Educational Eye And Face Protection, ANSI Standard Z87.1, from American National Standards Institute, 11 West 42nd Street, New York, NY 10036-8002 (phone: 212-642-4900, website: www.ansi.org).

Standard for Fire Prevention During Welding, Cutting, and Other Hot Work, NFPA Standard 51B, from National Fire Protection Association, P.O. Box 9101, 1 Battery March Park, Quincy, MA 02269-9101 (phone: 617-770-3000, website: www.nfpa.org and www.sparky.org).

OSHA, Occupational Safety and Health Standards for General Industry, Title 29, Code of Federal Regulations (CFR), Part 1910, Subpart Q, and Part 1926, Subpart J, from U.S. Government Printing Office, Superintendent of Documents, P.O. Box 371954, Pittsburgh, PA 15250 (there are 10 Regional Offices—phone for Region 5, Chicago, is 312-353-2220, website: www.osha.gov).

1-8. EMF Information

Considerations About Welding And The Effects Of Low Frequency Electric And Magnetic Fields

Welding current, as it flows through welding cables, will cause electromagnetic fields. There has been and still is some concern about such fields. However, after examining more than 500 studies spanning 17 years of research, a special blue ribbon committee of the National Research Council concluded that: "The body of evidence, in the committee's judgment, has not demonstrated that exposure to power-frequency electric and magnetic fields is a human-health hazard." However, studies are still going forth and evidence continues to be examined. Until the final conclusions of the research are reached, you may wish to minimize your exposure to electromagnetic fields when welding or cutting.

To reduce magnetic fields in the workplace, use the following procedures:

1. Keep cables close together by twisting or taping them.
2. Arrange cables to one side and away from the operator.
3. Do not coil or drape cables around your body.
4. Keep welding power source and cables as far away from operator as practical.
5. Connect work clamp to workpiece as close to the weld as possible.

About Pacemakers:

Pacemaker wearers consult your doctor first. If cleared by your doctor, then following the above procedures is recommended.

SECTION 2 – CONSIGNES DE SÉCURITÉ – LIRE AVANT UTILISATION

rom_fre 8/03

▲ Avertissement: Protégez vous et les autres des blessures – lisez et suivez ces précautions.

2-1. Signification des symboles



Signifie Mise en garde ! Soyez vigilant ! Cette procédure présente des risques de danger ! Ceux-ci sont identifiés par des symboles adjacents aux directives.

▲ Identifie un message de sécurité particulier.

☞ Signifie NOTA ; n'est pas relatif à la sécurité.



Ce groupe de symboles signifie Mise en garde ! Soyez vigilant ! Il y a des risques de danger reliés aux CHOCS ÉLECTRIQUES, aux PIÈCES EN MOUVEMENT et aux PIÈCES CHAUDES. Reportez-vous aux symboles et aux directives ci-dessous afin de connaître les mesures à prendre pour éviter tout danger.

2-2. Dangers relatifs au soudage à l'arc

- ▲ Les symboles présentés ci-après sont utilisés tout au long du présent manuel pour attirer votre attention et identifier les risques de danger. Lorsque vous voyez un symbole, soyez vigilant et suivez les directives mentionnées afin d'éviter tout danger. Les consignes de sécurité présentées ci-après ne font que résumer l'information contenue dans les normes de sécurité énumérées à la section 2-6. Veuillez lire et respecter toutes ces normes de sécurité.
- ▲ L'installation, l'utilisation, l'entretien et les réparations ne doivent être confiés qu'à des personnes qualifiées.
- ▲ Au cours de l'utilisation, tenir toute personne à l'écart et plus particulièrement les enfants.



UN CHOC ÉLECTRIQUE peut tuer.


Un simple contact avec des pièces électriques peut provoquer une électrocution ou des blessures graves. L'électrode et le circuit de soudage sont sous tension dès que l'appareil est sur ON. Le circuit d'entrée et les circuits internes de l'appareil sont également sous tension à ce moment-là. En soudage semi-automatique ou automatique, le fil, le dévidoir, le logement des galets d'entraînement et les pièces métalliques en contact avec le fil de soudage sont sous tension. Des matériaux mal installés ou mal mis à la terre présentent un danger.

- Ne jamais toucher les pièces électriques sous tension.
- Porter des gants et des vêtements de protection secs ne comportant pas de trous.
- S'isoler de la pièce et de la terre au moyen de tapis ou d'autres moyens isolants suffisamment grands pour empêcher le contact physique éventuel avec la pièce ou la terre.
- Ne pas se servir de source électrique àcourant électrique dans les zones humides, dans les endroits confinés ou là où on risque de tomber.
- Se servir d'une source électrique àcourant électrique UNIQUEMENT si le procédé de soudage le demande.
- Si l'utilisation d'une source électrique àcourant électrique s'avère nécessaire, se servir de la fonction de télécommande si l'appareil en est équipé.
- Des précautions de sécurité supplémentaires sont requises dans des environnements à risque comme: les endroits humides ou lorsque l'on porte des vêtements mouillés; sur des structures métalliques au sol, grillages et échafaudages; dans des positions assises, à genoux et allongées; ou quand il y a un risque important de contact accidentel avec la pièce ou le sol. Dans ces cas utiliser les appareils suivants dans l'ordre de préférence: 1) un poste à souder DC semi-automatique de type CV (MIG/MAG), 2) un poste à souder manuel (électrode enrobée) DC, 3) un poste à souder manuel AC avec tension à vide réduite. Dans la plupart des cas, un poste courant continu de type CV est recommandé. Et, ne pas travailler seul!
- Couper l'alimentation ou arrêter le moteur avant de procéder à l'installation, à la réparation ou à l'entretien de l'appareil. Déverrouiller l'alimentation selon la norme OSHA 29 CFR 1910.147 (voir normes de sécurité).
- Installer et mettre à la terre correctement cet appareil conformément à son manuel d'utilisation et aux codes nationaux, provinciaux et municipaux.
- Toujours vérifier la terre du cordon d'alimentation – Vérifier et s'assurer que le fil de terre du cordon d'alimentation est bien raccordé à la borne de terre du sectionneur ou que la fiche du cordon est raccordée à une prise correctement mise à la terre.

- En effectuant les raccordements d'entrée fixer d'abord le conducteur de mise à la terre approprié et contre-vérifier les connexions.
- Vérifier fréquemment le cordon d'alimentation pour voir s'il n'est pas endommagé ou dénudé – remplacer le cordon immédiatement s'il est endommagé – un câble dénudé peut provoquer une électrocution.
- Mettre l'appareil hors tension quand on ne l'utilise pas.
- Ne pas utiliser des câbles usés, endommagés, de grossoir insuffisante ou mal épissés.
- Ne pas enrouler les câbles autour du corps.
- Si la pièce soudée doit être mise à la terre, le faire directement avec un câble distinct – ne pas utiliser le connecteur de pièce ou le câble de retour.
- Ne pas toucher l'électrode quand on est en contact avec la pièce, la terre ou une électrode provenant d'une autre machine.
- N'utiliser qu'un matériel en bon état. Réparer ou remplacer sur-le-champ les pièces endommagées. Entretenir l'appareil conformément à ce manuel.
- Porter un harnais de sécurité quand on travaille en hauteur.
- Maintenir solidement en place tous les panneaux et capots.
- Fixer le câble de retour de façon à obtenir un bon contact métal-métal avec la pièce à souder ou la table de travail, le plus près possible de la soudure.
- Isoler la pince de masse quand pas mis à la pièce pour éviter le contact avec tout objet métallique.

Une tension DC importante subsiste à l'intérieur des onduleurs après avoir coupé l'alimentation.

- Couper l'alimentation du poste et décharger les condensateurs d'entrée comme indiqué dans la Section Maintenance avant de toucher des composants.



LES FUMÉES ET LES GAZ peuvent être dangereux.


Le soudage génère des fumées et des gaz. Leur inhalation peut être dangereux pour votre santé.

- Eloigner votre tête des fumées. Ne pas respirer les fumées.
- À l'intérieur, ventiler la zone et/ou utiliser un échappement au niveau de l'arc pour l'évacuation des fumées et des gaz de soudage.
- Si la ventilation est insuffisante, utiliser un respirateur à alimentation d'air homologué.
- Lire les spécifications de sécurité des matériaux (MSDSs) et les instructions du fabricant concernant les métaux, les consommables, les revêtements, les nettoyants et les dégraissants.
- Travailler dans un espace fermé seulement s'il est bien ventilé ou en portant un respirateur à alimentation d'air. Demander toujours à un surveillant dûment formé de se tenir à proximité. Des fumées et des gaz de soudage peuvent déplacer l'air et abaisser le niveau d'oxygène provoquant des blessures ou des accidents mortels. S'assurer que l'air de respiration ne présente aucun danger.
- Ne pas souder dans des endroits situés à proximité d'opérations de dégraissage, de nettoyage ou de pulvérisation. La chaleur et les rayons de l'arc peuvent réagir en présence de vapeurs et former des gaz hautement toxiques et irritants.
- Ne pas souder des métaux munis d'un revêtement, tels que l'acier galvanisé, plaqué en plomb ou au cadmium à moins que le revêtement n'ait été enlevé dans la zone de soudure, que l'endroit soit bien ventilé, et si nécessaire, en portant un respirateur à alimentation d'air. Les revêtements et tous les métaux renfermant ces éléments peuvent dégager des fumées toxiques en cas de soudage.



LES ACCUMULATIONS DE GAZ risquent de provoquer des blessures ou même la mort.

- Fermer l'alimentation du gaz protecteur en cas de non utilisation.
- Veiller toujours à bien aérer les espaces confinés ou se servir d'un respirateur d'adduction d'air homologué.



LES RAYONS DE L'ARC peuvent provoquer des brûlures dans les yeux et sur la peau.

Le rayonnement de l'arc du procédé de soudage génère des rayons visibles et invisibles intenses (ultraviolets et infrarouges) susceptibles de provoquer des brûlures dans les yeux et sur la peau. Des étincelles sont projetées pendant le soudage.

- Porter un casque de soudage muni d'un écran de filtre approprié pour protéger votre visage et vos yeux pendant le soudage ou pour regarder (voir ANSI Z49.1 et Z87.1 énumérés dans les normes de sécurité).
- Porter des protections approuvés pour les oreilles si le niveau sonore est trop élevé.
- Utiliser des écrans ou des barrières pour protéger des tiers de l'éclair et de l'éblouissement; demander aux autres personnes de ne pas regarder l'arc.
- Porter des vêtements de protection constitué dans une matière durable, résistant au feu (laine ou cuir) et une protection des pieds.



LE SOUDAGE peut provoquer un incendie ou une explosion.

Le soudage effectué sur des conteneurs fermés tels que des réservoirs, tambours ou des conduites peut provoquer leur éclatement. Des étincelles peuvent être projetées de l'arc de soudure. La projection d'étincelles, des pièces chaudes et des équipements chauds peut provoquer des incendies et des brûlures. Le contact accidentel de l'électrode avec des objets métalliques peut provoquer des étincelles, une explosion, un surchauffement ou un incendie. Avant de commencer le soudage, vérifier et s'assurer que l'endroit ne présente pas de danger.

- Se protéger et d'autres personnes de la projection d'étincelles et de métal chaud.
- Ne pas souder dans un endroit là où des étincelles peuvent tomber sur des substances inflammables.
- Déplacer toutes les substances inflammables à une distance de 10,7 m de l'arc de soudage. En cas d'impossibilité les recouvrir soigneusement avec des protections homologués.
- Des étincelles et des matériaux chauds du soudage peuvent facilement passer dans d'autres zones en traversant de petites fissures et des ouvertures.
- Surveiller tout déclenchement d'incendie et tenir un extincteur à proximité.
- Le soudage effectué sur un plafond, plancher, paroi ou séparation peut déclencher un incendie de l'autre côté.
- Ne pas effectuer le soudage sur des conteneurs fermés tels que des réservoirs, tambours, ou conduites, à moins qu'ils n'aient été préparés correctement conformément à AWS F4.1 (voir les normes de sécurité).
- Brancher le câble sur la pièce le plus près possible de la zone de soudage pour éviter le transport du courant sur une longue distance par des chemins inconnus éventuels en provoquant des risques d'électrocution et d'incendie.
- Ne pas utiliser le poste de soudage pour dégeler des conduites gelées.
- En cas de non utilisation, enlever la baguette d'électrode du porte-électrode ou couper le fil à la pointe de contact.
- Porter des vêtements de protection dépourvus d'huile tels que des gants en cuir, une chemise en matériau lourd, des pantalons sans revers, des chaussures hautes et un couvre chef.
- Avant de souder, retirer toute substance combustible de vos poches telles qu'un allumeur au butane ou des allumettes.


2-3. Dangers existant en relation avec le moteur



LES ACCUMULATIONS DE GAZ risquent de provoquer des blessures ou même la mort.

- Fermer l'alimentation du gaz protecteur en cas de non utilisation.
- Veiller toujours à bien aérer les espaces confinés ou se servir d'un respirateur d'adduction d'air homologué.

- Suivre les recommandations dans OSHA 1910.252(a)(2)(iv) et NFPA 51B pour les travaux à chaud et avoir de la surveillance et un extincteur à proximité.



DES PARTICULES VOLANTES peuvent blesser les yeux.

Le soudage, l'écaillage, le passage de la pièce à la brosse en fil de fer, et le meulage génèrent des étincelles et des particules métalliques volantes. Pendant la période de refroidissement des soudures, elles risquent de projeter du laitier.


- Porter des lunettes de sécurité avec écrans latéraux ou un écran facial.



DES PIÈCES CHAUDES peuvent provoquer des brûlures graves.

- Prévoir une période de refroidissement avant d'effectuer des travaux d'entretien.
- Porter des gants et des vêtements de protection pour travailler sur un moteur chaud.


- Ne pas toucher à mains nues les parties chaudes du moteur ni les pièces récemment soudées.



LE BRUIT peut affecter l'ouïe.


Le bruit des processus et des équipements peut affecter l'ouïe.

- Porter des protections approuvés pour les oreilles si le niveau sonore est trop élevé.



LES CHAMPS MAGNÉTIQUES peuvent affecter les stimulateurs cardiaques.


- Porteurs de stimulateur cardiaque, restez à distance.
- Les porteurs d'un stimulateur cardiaque doivent d'abord consulter leur médecin avant de s'approcher des opérations de soudage à l'arc, de gougeage ou de soudage par points.



Si des BOUTEILLES sont endommagées, elles pourront exploser.


Des bouteilles de gaz protecteur contiennent du gaz sous haute pression. Si une bouteille est endommagée, elle peut exploser. Du fait que les bouteilles de gaz font normalement partie du procédé de soudage, les manipuler avec précaution.

- Protéger les bouteilles de gaz comprimé d'une chaleur excessive, des chocs mécaniques, du laitier, des flammes ouvertes, des étincelles et des arcs.
- Placer les bouteilles debout en les fixant dans un support stationnaire ou dans un porte-bouteilles pour les empêcher de tomber ou de se renverser.
- Tenir les bouteilles éloignées des circuits de soudage ou autres circuits électriques.
- Ne jamais placer une torche de soudage sur une bouteille à gaz.
- Une électrode de soudage ne doit jamais entrer en contact avec une bouteille.
- Ne jamais souder une bouteille pressurisée – risque d'explosion.
- Utiliser seulement des bouteilles de gaz protecteur, régulateurs, tuyaux et raccords convenables pour cette application spécifique; les maintenir ainsi que les éléments associés en bon état.
- Ne pas tenir la tête en face de la sortie en ouvrant la soupape de la bouteille.
- Maintenir le chapeau de protection sur la soupape, sauf en cas d'utilisation ou de branchement de la bouteille.
- Lire et suivre les instructions concernant les bouteilles de gaz comprimé, les équipements associés et les publication P-1 CGA énumérées dans les normes de sécurité.



L'ACIDE DE LA BATTERIE peut provoquer des brûlures dans les YEUX et sur la PEAU.

- Ne pas renverser la batterie.
- Remplacer une batterie endommagée.
- Rincer immédiatement les yeux et la peau à l'eau.



L'EXPLOSION DE LA BATTERIE peut RENDRE AVEUGLE.

- Toujours porter une protection faciale, des gants en caoutchouc et vêtements de protection lors d'une intervention sur la batterie.
- Arrêter le moteur avant de débrancher ou de brancher les câbles de batterie.
- Eviter de provoquer des étincelles avec les outils en travaillant sur la batterie.
- Ne pas utiliser le poste de soudage pour charger les batteries ou des véhicules de démarrage rapide.
- Observer la polarité correcte (+ et -) sur les batteries.
- Débrancher le câble négatif (-) en premier lieu. Le rebrancher en dernier lieu.



LE CARBURANT MOTEUR peut provoquer un incendie ou une explosion.


- Arrêter le moteur avant de vérifier le niveau de carburant ou de faire le plein.
- Ne pas faire le plein en fumant ou proche d'une source d'étincelles ou d'une flamme nue.
- Ne pas faire le plein de carburant à ras bord; prévoir de l'espace pour son expansion.
- Faire attention de ne pas renverser de carburant. Nettoyer tout carburant renversé avant de faire démarrer le moteur.
- Jeter les chiffons dans un récipient ignifuge.



DES ORGANES MOBILES peuvent provoquer des blessures.

- Ne pas approcher les mains des ventilateurs, courroies et autres pièces en mouvement.
- Maintenir fermés et fixement en place les portes, panneaux, recouvrements et dispositifs de protection.
- Arrêter le moteur avant d'installer ou brancher l'appareil.
- Demander seulement à un personnel qualifié d'enlever les dispositifs de sécurité ou les recouvrements pour effectuer, s'il y a lieu, des travaux d'entretien et de dépannage.


- Pour empêcher tout démarrage accidentel pendant les travaux d'entretien, débrancher le câble négatif (-) de batterie de la borne.
- Ne pas approcher les mains, cheveux, vêtements lâches et outils des organes mobiles.
- Remettre en place les panneaux ou les dispositifs de protection et fermer les portes à la fin des travaux d'entretien et avant de faire démarrer le moteur.
- Avant d'intervenir, déposer les bougies ou injecteurs pour éviter la mise en route accidentelle du moteur.
- Bloquer le volant moteur pour éviter sa rotation lors d'une intervention sur le générateur.



LA VAPEUR ET LE LIQUIDE DE REFROIDISSEMENT CHAUD peuvent provoquer des brûlures.

- Il est préférable de vérifier le liquide de refroidissement une fois le moteur refroidi pour éviter de se brûler.

- Toujours vérifier le niveau de liquide de refroidissement dans le vase d'expansion (si présent), et non dans le radiateur (sauf si précisé autrement dans la section maintenance du manuel du moteur).
- Si le moteur est chaud et que le liquide doit être vérifié, opérer comme suivant :
- Mettre des lunettes de sécurité et des gants, placer un torchon sur le bouchon du radiateur.
- Dévisser le bouchon légèrement et laisser la vapeur s'échapper avant d'enlever le bouchon.



LA CHALEUR DU MOTEUR peut provoquer un incendie.

- Ne pas placer l'appareil sur, au-dessus ou à proximité de surfaces inflammables.
- Tenir à distance les produits inflammables de l'échappement.



LES ÉTINCELLES À L'ÉCHAPPEMENT peuvent provoquer un incendie.


- Empêcher les étincelles d'échappement du moteur de provoquer un incendie.
- Utiliser uniquement un pare-étincelles approuvé – voir codes en vigueur.

2-4. Dangers liés à l'air comprimé




RESPIRER L'AIR COMPRIMÉ peut provoquer des blessures graves ou causer la mort.

- Ne pas utiliser l'air comprimé pour respirer.
- Utiliser l'air comprimé seulement pour le coupage, gougeage et les outils pneumatiques.



L'AIR COMPRIMÉ peut provoquer des blessures.

- Porter des lunettes de sécurité approuvées.
- Ne pas diriger le jet d'air vers d'autres ou soi-même.



L'AIR COMPRIME EMMAGASINE ET DES TUYAUX SOUS PRESSION peuvent provoquer des blessures.

- Relâcher la pression d'air de l'outil ou du système avant d'effectuer la maintenance, avant de changer ou de rajouter des éléments ou avant d'ouvrir la purge ou le bouchon de remplissage d'huile.




Le METAL CHAUD lors du coupage et gougeage plasma peut provoquer un incendie ou une explosion.

- Ne pas couper ou gouger à proximité de produits inflammables.
- Surveillez et garder un extincteur à proximité.



DES PIÈCES CHAUDES peuvent provoquer des brûlures et blessures.

- Ne pas toucher le compresseur ou d'autres éléments du circuit air comprimé chauds.
- Laisser l'ensemble se refroidir avant de toucher ou d'effectuer la maintenance.



LIRE LES INSTRUCTIONS.

- Lisez le manuel d'instructions avant l'utilisation ou la maintenance de l'appareil.
- Arrêter le moteur et relâcher la pression avant d'effectuer la maintenance.


2-5. Dangers supplémentaires en relation avec l'installation, le fonctionnement et la maintenance



LA CHUTE DE L'APPAREIL peut blesser.


- Utiliser l'anneau de levage uniquement pour soulever l'appareil lui-même ; sans chariot, de bouteilles de gaz, remorque, ou autres accessoires.

- Utiliser un équipement de levage de capacité suffisante pour lever l'appareil.
- En utilisant des fourches de levage pour déplacer l'unité, s'assurer que les fourches sont suffisamment longues pour dépasser du côté opposé de l'appareil.



LE SURCHAUFFEMENT peut endommager le moteur électrique.


- Arrêter ou déconnecter l'équipement avant de démarrer ou d'arrêter le moteur.
- Ne pas laisser tourner le moteur trop lentement sous risque d'endommager le moteur électrique à cause d'une tension et d'une fréquence trop faibles.
- Ne pas brancher de moteur de 50 ou de 60 Hz à la prise de 100 Hz, s'il y a lieu.



LES ÉTINCELLES VOLANTES risquent de provoquer des blessures.


- Porter un écran facial pour protéger le visage et les yeux.

- Affuter l'électrode au tungstène uniquement à la meuleuse dotée de protecteurs. Cette manœuvre est à exécuter dans un endroit sûr lorsque l'on porte l'équipement homologué de protection du visage, des mains et du corps.
- Les étincelles risquent de causer un incendie – éloigner toute substance inflammable.



L'EMPLOI EXCESSIF peut SURCHAUFFER L'ÉQUIPEMENT.

- Laisser l'équipement refroidir ; respecter le facteur de marche nominal.
- Réduire le courant ou le facteur de marche avant de poursuivre le soudage.
- Ne pas obstruer les passages d'air du poste.




LES CHARGES ÉLECTROSTATIQUES peuvent endommager les circuits imprimés.

- Établir la connexion avec la barrette de terre avant de manipuler des cartes ou des pièces.
- Utiliser des pochettes et des boîtes antistatiques pour stocker, déplacer ou expédier des cartes de circuits imprimés.




UNE REMORQUE QUI BASCULE peut entraîner des blessures.

- Utiliser les supports de la remorque ou des blocs pour soutenir le poids.
- Installer convenablement le poste sur la remorque comme indiqué dans le manuel s'y rapportant.




LIRE LES INSTRUCTIONS.

- Utiliser seulement les pièces de rechange d'origine.
- Effectuer la maintenance du moteur et du compresseur (si applicable) suivant ce manuel et le manuel du moteur/compresseur (si applicable).



LE RAYONNEMENT HAUTE FRÉQUENCE (H.F.) risque de provoquer des interférences.

- Le rayonnement haute fréquence (H.F.) peut provoquer des interférences avec les équipements de radio-navigation et de communication, les services de sécurité et les ordinateurs.
- Demander seulement à des personnes qualifiées familiarisées avec des équipements électroniques de faire fonctionner l'installation.
- L'utilisateur est tenu de faire corriger rapidement par un électricien qualifié les interférences résultant de l'installation.
- Si le FCC signale des interférences, arrêter immédiatement l'appareil.
- Effectuer régulièrement le contrôle et l'entretien de l'installation.
- Maintenir soigneusement fermés les portes et les panneaux des sources de haute fréquence, maintenir les éclateurs à une distance correcte et utiliser une terre et un blindage pour réduire les interférences éventuelles.



LE SOUDAGE À L'ARC risque de provoquer des interférences.

- L'énergie électromagnétique risque de provoquer des interférences pour l'équipement électronique sensible tel que les ordinateurs et l'équipement commandé par ordinateur tel que les robots.
- Veiller à ce que tout l'équipement de la zone de soudage soit compatible électromagnétiquement.
- Pour réduire la possibilité d'interférence, maintenir les câbles de soudage aussi courts que possible, les grouper, et les poser aussi bas que possible (ex. par terre).
- Veiller à souder à une distance de 100 mètres de tout équipement électronique sensible.
- Veiller à ce que ce poste de soudage soit posé et mis à la terre conformément à ce mode d'emploi.
- En cas d'interférences après avoir pris les mesures précédentes, il incombe à l'utilisateur de prendre des mesures supplémentaires telles que le déplacement du poste, l'utilisation de câbles blindés, l'utilisation de filtres de ligne ou la pose de protecteurs dans la zone de travail.

2-6. Principales normes de sécurité

Safety in Welding, Cutting, and Allied Processes, norme ANSI Z49.1, de l'American Welding Society, 550 N.W. LeJeune Rd, Miami FL 33126 (téléphone : (305) 443-9353, site Web : www.aws.org).

Recommended Safe Practices for the Preparation for Welding and Cutting of Containers and Piping, norme American Welding Society AWS F4.1, de l'American Welding Society, 550 N.W. LeJeune Rd, Miami, FL 33126 (téléphone : (305) 443-9353, site Web : www.aws.org).

National Electrical Code, norme NFPA 70, de la National Fire Protection Association, P.O. Box 9101, 1 Battery March Park, Quincy, MA 02269-9101 (téléphone : (617) 770-3000, sites Web : www.nfpa.org et www.sparky.org).

Safe Handling of Compressed Gases in Cylinders, brochure CGA P-1, de la Compressed Gas Association, 1735 Jefferson Davis Highway, Suite 1004, Arlington, VA 22202-4102 (téléphone : (703) 412-0900, site Web : www.cganet.com).

Code for Safety in Welding and Cutting, norme CSA W117.2, de la Canadian Standards Association, Standards Sales, 178 boulevard Rexdale, Rexdale (Ontario) Canada M9W 1R3 (téléphone : (800) 463-6727 ou à Toronto : (416) 747-4044, site Web : www.csa-international.org).

Practice For Occupational And Educational Eye And Face Protection, norme ANSI Z87.1, de l'American National Standards Institute, 11 West 42nd Street, New York, NY 10036-8002 (téléphone : (212) 642-4900, site Web : www.ansi.org).

Standard for Fire Prevention During Welding, Cutting, and Other Hot Work, norme NFPA 51B, de la National Fire Protection Association, P.O. Box 9101, 1 Battery March Park, Quincy, MA 02269-9101 (téléphone : (617) 770-3000, site Web : www.nfpa.org et www.sparky.org).

OSHA, Occupational Safety and Health Standards for General Industry, Title 29, Code of Federal Regulations (CFR), Part 1910, Subpart Q, and Part 1926, Subpart J, de l'U.S. Government Printing Office, Superintendent of Documents, P.O. Box 371954, Pittsburgh, PA 15250 (il y a 10 bureaux régionaux – Téléphone pour la Région 5, Chicago : (312) 353-2220, site Web : www.osha.gov).

2-7. Information sur les champs électromagnétiques

Données sur le soudage électrique et les effets des champs magnétiques basse fréquence sur l'organisme

En parcourant les câbles de soudage, le courant crée des champs électromagnétiques. Les effets potentiels de tels champs restent préoccupants. Cependant, après avoir examiné plus de 500 études qui ont été faites pendant une période de recherche de 17 ans, un comité de spécialistes du National Research Council a conclu : « L'accumulation de preuves n'a pas démontré que l'exposition aux champs magnétiques et aux champs électriques à haute fréquence constitue un risque pour la santé humaine ». Toutefois, les études et l'examen des preuves se poursuivent. En attendant les conclusions finales de la recherche, il serait souhaitable de réduire l'exposition aux champs électromagnétiques pendant le soudage ou le coupage.

Afin de réduire les champs électromagnétiques en milieu de travail, respecter les consignes suivantes :

1. Garder les câbles ensemble en les torsadant ou en les fixant avec du ruban adhésif.
2. Mettre tous les câbles du côté opposé à l'opérateur.
3. Ne pas s'enrouler les câbles autour du corps.
4. Garder le poste de soudage et les câbles le plus loin possible de soi.
5. Placer la pince de masse le plus près possible de la zone de soudage.

Consignes relatives aux stimulateurs cardiaques :


















Les personnes qui portent un stimulateur cardiaque doivent avant tout consulter leur médecin. Si ce dernier les déclare aptes, il leur est recommandé de respecter les consignes ci-dessus.

SECTION 3 – DEFINITIONS

3-1. Warning Label Definitions (For Wordless Labels)




Warning! Watch Out! There are possible hazards as shown by the symbols.


Become trained and read the instructions before working on the machine or welding.

							
1	1.1	1.2	1.3	2	2.1	2.2	2.3
							
3	3.1	3.2	3.3	4	4.1	5	
							
6	6.1	6.2	6.3				
							
7	7.1	7.2					
							


176 105-B

- 1 Electric shock from welding electrode or wiring can kill.
- 1.1 Wear dry insulating gloves. Do not touch electrode with bare hand. Do not wear wet or damaged gloves.
- 1.2 Protect yourself from electric shock by insulating yourself from work and ground.
- 1.3 Do not work on unit if engine is running. Stop engine first.
- 2 Breathing welding fumes can be hazardous to your health.
 - 2.1 Keep your head out of the fumes.
 - 2.2 Use forced ventilation or local exhaust to remove the fumes.
 - 2.3 Use ventilating fan to remove fumes.
- 3 Welding sparks can cause explosion or fire.
 - 3.1 Keep flammables away from welding. Do not weld near flammables.
 - 3.2 Welding sparks can cause fires. Have a fire extinguisher nearby, and have a watchperson ready to use it.
 - 3.3 Do not weld on drums or any closed containers.
- 4 Arc rays can burn eyes and injure skin.
 - 4.1 Wear hat and safety glasses. Use ear protection and button shirt collar. Use welding helmet with correct shade of filter. Wear complete body protection.
 - 5 Do not remove or paint over (cover) the label.
- 6 Engine fuel plus flames or sparks can cause fire.
 - 6.1 Do not smoke while fueling or if near fuel.
 - 6.2 Stop engine before fueling.
 - 6.3 Do not fuel a hot engine.
- 7 Engine exhaust gases can kill.
 - 7.1 Vent exhaust outside.
 - 7.2 Use unit outside.








3/96




3/96



3/96





3-2. Manufacturer's Rating Labels For Non-CE Products

CC Models				CC/CV Models																											
		ISO / IEC 60974-1				ISO / IEC 60974-1																									
	U ₀ = 92V	55A/22V to 500A/40V		45A/22V to 500A/40V		20A/11V to 300A/22V																									
		X		60%	100%	X		60%	100%																						
		I ₂		500A	400A	I ₂		500A	400A																						
	U ₀ = 92V	U ₂		40V		36V		U ₂		40V		36V																			
		55A/12V to 530A/31V		530A/31V		300A/22V		300A/22V																							
		X	40%	60%	100%	X			100%	I ₂		300A	I ₂		300A																
	U ₀ = 92V	I ₂		530A		500A		U ₂		31V		30V		26V																	
		U ₂		31V		30V		26V		U ₂		31V		30V																	
		n = 1800 min ⁻¹				n = 1800 min ⁻¹																									
IP 23		n ₀ = 1850 min ⁻¹ n ₁ = 1235 min ⁻¹		IP 23		n ₀ = 1850 min ⁻¹ n ₁ = 1235 min ⁻¹																									
1 ~ 60 Hz		120/240V		4kVA		20/15A		1 ~ 60 Hz		120/240V		4kVA		20/15A																	
200 784																200 783															

3-3. Manufacturer's Rating Labels For CE Products

CC Models				CC/CV Models															
		ISO / IEC 60974-1				ISO / IEC 60974-1													
		55A/22V		to		500A/40V													
		X		60%		100%													
		I ₂		500A		400A													
		U ₂		40V		36V													
		55A/12V		to		530A/31V													
		X	40%	60%	100%														
		I ₂	530A	500A	400A														
		U ₂	31V	30V	26V														
																			
n = 1800 min⁻¹																			
		n ₀ = 1850 min ⁻¹	n ₁ = 1235 min ⁻¹																
IP 23																			
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="padding: 5px;">1~ 60 Hz</td><td style="padding: 5px;">110V</td><td style="padding: 5px;">4.0kVA</td><td style="padding: 5px;">36A</td></tr> <tr> <td style="padding: 5px;">1~ 60 Hz</td><td style="padding: 5px;">230V</td><td style="padding: 5px;">3.7kVA</td><td style="padding: 5px;">16A</td></tr> <tr> <td style="padding: 5px;"></td><td style="padding: 5px;"></td><td style="padding: 5px;"></td><td style="padding: 5px;"></td></tr> </table>		1~ 60 Hz	110V					4.0kVA	36A	1~ 60 Hz	230V	3.7kVA	16A						
1~ 60 Hz	110V	4.0kVA	36A																
1~ 60 Hz	230V	3.7kVA	16A																
																			
n = 1800 min⁻¹																			
		n ₀ = 1850 min ⁻¹	n ₁ = 1235 min ⁻¹																
IP 23																			
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="padding: 5px;">1~ 60 Hz</td><td style="padding: 5px;">110V</td><td style="padding: 5px;">4.0kVA</td><td style="padding: 5px;">36A</td></tr> <tr> <td style="padding: 5px;">1~ 60 Hz</td><td style="padding: 5px;">230V</td><td style="padding: 5px;">3.7kVA</td><td style="padding: 5px;">16A</td></tr> <tr> <td style="padding: 5px;"></td><td style="padding: 5px;"></td><td style="padding: 5px;"></td><td style="padding: 5px;"></td></tr> </table>		1~ 60 Hz	110V					4.0kVA	36A	1~ 60 Hz	230V	3.7kVA	16A						
1~ 60 Hz	110V	4.0kVA	36A																
1~ 60 Hz	230V	3.7kVA	16A																

Notes

MATERIAL THICKNESS REFERENCE CHART

	24 Gauge (.025 in)
	22 Gauge (.031 in)
	20 Gauge (.037 in)
	18 Gauge (.050 in)
	16 Gauge (.063 in)
	14 Gauge (.078 in)
	1/8 in (.125 in)
	3/16 in (.188 in)
	1/4 in (.25 in)
	5/16 in (.313 in)
	3/8 in (.375 in)
	1/2 in (.5 in)

3-4. Symbols And Definitions



	Stop Engine		Fast (Run, Weld Power)		Slow (Idle)		Start Engine
	Starting Aid		Battery (Engine)		Engine Oil Pressure		Engine Oil
	Check Injectors/ Pump		Check Valve Clearance		Fuel		Protective Earth (Ground)
	Positive		Negative		Certified/Trained Mechanic		Welding Arc
	Ampères		Volts		Panel/Local		Remote
	Engine		Air Temperature Or Engine Temperature		Output		Alternating Current
	Stick (SMAW) Welding		Constant Current (CC)		MIG (GMAW) Welding		TIG (GTAW)
	Time		Hours		Seconds		Single Phase
	Three Phase		Read Operator's Manual		Circuit Breaker		Do Not Switch While Welding
	Electrode Connection		Work Connection		Engine-Driven, Three-Phase Alternator With Rectifier		Hertz
	Duty Cycle		Rated No Load Voltage (Average)		Conventional Load Voltage		Rated Load Speed
	Rated Idle Speed		Rated No Load Speed		Current		Rated Welding Current
	Contactor On						

SECTION 4 – SPECIFICATIONS


4-1. Weld, Power, And Engine Specifications

Welding Mode	Weld Output Range	Rated Welding Output	Maximum Open-Circuit Voltage	Generator Power Rating	Engine	Fuel Capacity
CC/DC	55 – 600 A (CC Models) 20 – 600 A (CC/CV Models)	Deutz F4L2011-Powered Units: 400 A, 40 Volts DC, 100% Duty Cycle 500 A, 40 volts DC, 60% Duty Cycle 600 A, 30 Volts DC, 40% Duty Cycle	95	Standard: Single-Phase, 4 kVA/kW, 34/17 A, 120/240 V AC, 50/60 Hz Three-Phase Generator Option:* Single-Phase/Three-Phase, 12/20 kVA/kW, 50/48A, 120/240 VAC, 60 Hz	 Deutz F4L2011 Air/Oil-Cooled, Four Cylinder, 44 HP Diesel Engine or Deutz F3L912, Air-Cooled, Three Cylinder, 41.5 HP Diesel Engine	25 gal (95 L)
CV/DC (CC/CV Models Only)	14 – 40 V	Deutz F3L912-Powered Units: 500 A, 40 volts DC, 100% Duty Cycle 600 A, 30 Volts DC, 40% Duty Cycle	56	*In Addition To Standard 4 kVA/kW Generator Power		

4-2. Dimensions, Weights, And Operating Angles

Dimensions		 <p>802 161-A</p>	 <ul style="list-style-type: none"> Do not exceed tilt angles or engine could be damaged or unit could tip. Do not move or operate unit where it could tip.  <p>802 311</p>	
Height	50 in (1270 mm) (to top of muffler)			
Width	28-1/2 in (724 mm) (mtg. brackets turned in) 30-3/4 in (781 mm) (mtg. brackets turned out)			
Depth	65-1/8 in (1654 mm)			
A	65-1/8 in (1654 mm)			
B*	56 in (1422 mm)			
C*	46-1/2 in (1181)			
D*	9-5/8 in (244 mm)			
E	27-1/2 in (699 mm)			
F	1 in (25 mm)			
G	29-1/2 in (749 mm)			
H	9/16 in (14 mm) Dia. 4 Holes			
* With mounting brackets in center position. Dimensions vary with location of mounting brackets.				
Weight				
w/ Deutz F4L2011	No fuel: 1690 lb (767 kg) w/fuel: 1880 lb (853 kg)			
w/ Deutz F3L912	No fuel: 1785 lb (810 kg) w/fuel: 1975 lb (896 kg)			


4-3. Volt-Ampere Curves For CC Models



Notes


4-4. Volt-Ampere Curves For CC/CV Models

A. Stick Mode




The volt-ampere curves show the minimum and maximum voltage and amperage output capabilities of the welding generator. Curves of all other settings fall between the curves shown.


B. MIG Mode



C. TIG Mode



4-5. Fuel Consumption




Notes

4-6. Duty Cycle And Overheating




A. Deutz F4L-1011-Powered Units

100% Duty Cycle At 400 Amperes




Continuous Welding




B. Deutz F3L912-Powered Units

100% Duty Cycle At 500 Amperes



Continuous Welding




Duty Cycle is percentage of 10 minutes that unit can weld at rated load without overheating.

▲ Exceeding duty cycle can damage unit and void warranty.

4-7. AC Generator Power Curve

The ac power curve shows the generator power in amperes available at the 120 and 240 volt receptacles.




193 018

Notes


4-8. Optional Three-Phase Generator Curves

A. 12 kVA/kW Single-Phase AC Output (No Weld Load)



The ac power curves show the generator power available in amperes at the single-phase 120/240 volt receptacle or three-phase 240 volt terminals.

B. 20 kVA/kW Three-Phase AC Output (No Weld Load)



Notes



HOBART INSTITUTE OF WELDING TECHNOLOGY

400 Trade Square East, Troy, Ohio 45373
1-800-332-9448 www.welding.org

Start Your Professional Welding Career Now!


**Over 80,000 trained
since 1930!**

SECTION 5 – INSTALLATION


5-1. Installing Welding Generator (See Sections 5-2 And 5-3)




Movement



Location




Grounding



▲ Bed liners, shipping skids, and some running gears insulate the welding generator from the vehicle frame. Always connect a ground wire from the generator equipment grounding terminal to bare metal on the vehicle frame as shown.

Airflow Clearance



▲ Always securely fasten welding generator onto transport vehicle or trailer and comply with all DOT and other applicable codes.

▲ Always ground generator frame to vehicle frame to prevent electric shock and static electricity hazards.

▲ If unit does not have GFCI receptacles, use GFCI-protected extension cord.

☞ See Section 5-3 for mounting information.

Grounding:


1 Equipment Grounding Terminal (On Front Panel)

2 Grounding Cable (Not Supplied)


3 Metal Vehicle Frame

Connect cable from equipment ground terminal to metal vehicle frame. Use #10 AWG or larger insulated copper wire.

5-2. Using Lifting Eye



Notes




Work like a Pro!

Pros weld and cut safely. Read the safety rules at the beginning of this manual.


5-3. Mounting Welding Generator



Supporting The Unit



▲ Do not use flexible mounts.



▲ Do not weld on base. Welding on base can cause fuel tank fire or explosion. Weld only on the four mounting brackets or bolt unit down.

▲ Do not mount unit by supporting the base only at the four mounting brackets. Use cross-supports to adequately support unit and prevent damage to base.

Mounting Surface:

- 1 Cross-Supports
- 2 Mounting Brackets (Supplied)

Mount unit on flat surface or use cross-supports to support base. Secure unit with mounting brackets.

- 3 1/2 in Bolt And Washer (Minimum – Not Supplied)
- 4 3/8-16 x 1 in Screws (Supplied)

To Bolt Unit In Place:



Remove hardware securing the four mounting brackets to the base. Reverse brackets and reattach to base with original hardware.

Mount unit to truck or trailer with 1/2 in (12 mm) or larger hardware (not supplied).


To Weld Unit In Place:

Weld unit to truck or trailer only at the four mounting brackets.

Using Mounting Brackets




Tools Needed:




9/16 in


5-4. Installing Exhaust Pipe



5-5. Installing Engine Side Baffle (CE Models Only)



5-6. Activating The Dry Charge Battery (If Applicable)



Remove battery from unit.

- 1 Eye Protection – Safety Glasses Or Face Shield
- 2 Rubber Gloves
- 3 Vent Caps
- 4 Sulfuric Acid Electrolyte (1.265 Specific Gravity)
- 5 Well

Fill each cell with electrolyte to **bottom** of well (maximum).

▲ Do not overfill battery cells.




Wait ten minutes and check electrolyte level. If necessary, add electrolyte to raise to proper level. Reinstall vent caps.

- 6 Battery Charger

▲ Read and follow all instructions supplied with battery charger.

Charge battery for 12 minutes at 30 amperes or 30 minutes at 5 amperes. Disconnect charging cables and install battery.

When electrolyte is low, add only distilled water to cells to maintain proper level.




5 A For 30 Minutes


OR



30 A For 12 Minutes



Tools Needed:




rubber gloves




glasses

drybatt1 1/98 – 0886



5-7. Connecting The Battery



5-8. Installing Optional Ether Cylinder (Deutz F3L912 Engine Only)



5-9. Engine Prestart Checks



Check all engine fluids daily.

Engine must be cold and on a level surface. Unit is shipped with 20W break-in oil. The Automatic shutdown system stops engine if oil pressure is too low or coolant temperature is too high.

This unit has a low oil pressure shutdown switch. However, some conditions may cause engine damage before the engine shuts down. Check oil level often and do not use the oil pressure shutdown system to monitor oil level.

Follow run-in procedure in engine manual.

If unburned fuel and oil collect in exhaust pipe during run-in, see Section 13.

Fuel

Do not use gasoline. Gasoline will damage engine.

Add fresh diesel fuel before starting to prevent air from entering the fuel system (see engine maintenance label for fuel specifications). Leave filler neck empty to allow room for expansion.

Do not run out of fuel or air may enter fuel system and cause starting problems. See engine manual to bleed air from fuel system.

Oil

Ref. 802 313-A / 802 398-A
After fueling, check oil with unit on level surface. If oil is not up to full mark on dipstick, add oil (see maintenance label).


To improve cold weather starting:
Use optional Starting Aid switch (see Section 6-1 or 7-1).

Keep battery in good condition. Store battery in warm area.

Use fuel formulated for cold weather (diesel fuel can gel in cold weather). Contact local fuel supplier for fuel information.

Use correct grade oil for cold weather (see Section 9-2 or 10-2).

5-10. Connecting To Weld Output Terminals



▲ Stop engine.

- 1 Positive (+) Weld Output Terminal
- 2 Negative (-) Weld Output Terminal

For Stick and TIG welding Direct Current Electrode Positive (DCEP), connect electrode holder cable to Positive (+) terminal on left and work cable to Negative (-) terminal on right.

For Direct Current Electrode Negative (DCEN), reverse cable connections.

If equipped with optional polarity switch, connect electrode holder cable to Electrode terminal on left and work cable to Work terminal on right.

For MIG and FCAW welding Direct Current Electrode Positive (DCEP) on CC/CV models, connect wire feeder cable to Positive (+) terminal on left and work cable to Negative (-) terminal on right. Use Process/Contactor switch to select type of weld output (see Section 7-3).

For Direct Current Electrode Negative (DCEN), reverse cable connections.

If equipped with optional polarity switch, connect wire feeder cable to Electrode terminal on left and work cable to Work terminal on right.

802 311-A

5-11. Selecting Weld Cable Sizes*

Weld Output Terminals	Welding Amperes	Weld Cable Size** and Total Cable (Copper) Length in Weld Circuit Not Exceeding***							
		100 ft (30 m) or Less		150 ft (45 m)	200 ft (60 m)	250 ft (70 m)	300 ft (90 m)	350 ft (105 m)	400 ft (120 m)
		10 – 60% Duty Cycle	60 – 100% Duty Cycle	10 – 100% Duty Cycle					
▲ Stop engine before connecting to weld output terminals. ▲ Do not use worn, damaged, undersized, or poorly spliced cables.	100	4 (20)	4 (20)	4 (20)	3 (30)	2 (35)	1 (50)	1/0 (60)	1/0 (60)
	150	3 (30)	3 (30)	2 (35)	1 (50)	1/0 (60)	2/0 (70)	3/0 (95)	3/0 (95)
	200	3 (30)	2 (35)	1 (50)	1/0 (60)	2/0 (70)	3/0 (95)	4/0 (120)	4/0 (120)
	250	2 (35)	1 (50)	1/0 (60)	2/0 (70)	3/0 (95)	4/0 (120)	2 ea. 2/0 (2x70)	2 ea. 2/0 (2x70)
	300	1 (50)	1/0 (60)	2/0 (70)	3/0 (95)	4/0 (120)	2 ea. 2/0 (2x70)	2 ea. 3/0 (2x95)	2 ea. 3/0 (2x95)
	350	1/0 (60)	2/0 (70)	3/0 (95)	4/0 (120)	2 ea. 2/0 (2x70)	2 ea. 3/0 (2x95)	2 ea. 3/0 (2x95)	2 ea. 4/0 (2x120)
	400	1/0 (60)	2/0 (70)	3/0 (95)	4/0 (120)	2 ea. 2/0 (2x70)	2 ea. 3/0 (2x95)	2 ea. 4/0 (2x120)	2 ea. 4/0 (2x120)
	500	2/0 (70)	3/0 (95)	4/0 (120)	2 ea. 2/0 (2x70)	2 ea. 3/0 (2x95)	2 ea. 4/0 (2x120)	3 ea. 3/0 (3x95)	3 ea. 3/0 (3x95)


* This chart is a general guideline and may not suit all applications. If cable overheating occurs (normally you can smell it), use next size larger cable.

**Weld cable size (AWG) is based on either a 4 volts or less drop or a current density of at least 300 circular mils per ampere.
(-) = mm² for metric use

S-0007-E-

***For distances longer than those shown in this guide, call a factory applications representative at 920-735-4505.

5-12. Connecting To Remote Amperage Adjust Receptacle RC13 On CC Models



5-13. Connecting To Remote 14 Receptacle RC14 On CC/CV Models

New! LDR-14 long distance remote (includes 120 V receptacle)

OR

802 311

	Socket*	Socket Information
REMOTE 14		
24 VOLTS AC OUTPUT (CONTACTOR)	A	24 volts ac. Protected by circuit breaker CB5.
	B	Contact closure to A completes 24 volt ac contactor control circuit.
REMOTE OUTPUT CONTROL	C	Output to remote control: +10 volts dc in MIG or Stick mode; 0 to +10 volts dc in TIG mode.
	D	Remote control circuit common.
	E	DC input command signal: 0 to +10 volts from min. to max. of remote control with Voltage/ Amperage Adjust control at max.
115 VOLTS AC OUTPUT (CONTACTOR)	I	115 volts, 10 amperes, 60 Hz ac. Protected by circuit breaker CB6.
	J	Contact closure to I completes 115 volt ac contactor control circuit.
GND	K	Chassis common.
NEUTRAL	G	Circuit common for 24 and 115 volt ac circuit.

*The remaining sockets are not used.


Notes

DECIMAL EQUIVALENTS

$\frac{1}{64}$.015625
$\frac{3}{64}$.03125
$\frac{5}{64}$.046875
$\frac{7}{64}$.0625
$\frac{9}{64}$.078125
$\frac{11}{64}$.09375
$\frac{13}{64}$.109375
$\frac{15}{64}$.125
$\frac{17}{64}$.140625
$\frac{19}{64}$.15625
$\frac{21}{64}$.171875
$\frac{23}{64}$.1875
$\frac{25}{64}$.203125
$\frac{27}{64}$.21875
$\frac{29}{64}$.234375
$\frac{31}{64}$.25
$\frac{33}{64}$.265625
$\frac{35}{64}$.28125
$\frac{37}{64}$.296875
$\frac{39}{64}$.3125
$\frac{41}{64}$.328125
$\frac{43}{64}$.34375
$\frac{45}{64}$.359375
$\frac{47}{64}$.375
$\frac{49}{64}$.390625
$\frac{51}{64}$.40625
$\frac{53}{64}$.421875
$\frac{55}{64}$.4375
$\frac{57}{64}$.453125
$\frac{59}{64}$.46875
$\frac{61}{64}$.484375
$\frac{63}{64}$.5
$\frac{17}{32}$.515625
$\frac{19}{32}$.53125
$\frac{21}{32}$.546875
$\frac{23}{32}$.5625
$\frac{25}{32}$.578125
$\frac{27}{32}$.59375
$\frac{29}{32}$.609375
$\frac{31}{32}$.625
$\frac{33}{32}$.640625
$\frac{35}{32}$.65625
$\frac{37}{32}$.671875
$\frac{39}{32}$.6875
$\frac{41}{32}$.703125
$\frac{43}{32}$.71875
$\frac{45}{32}$.734375
$\frac{47}{32}$.75
$\frac{49}{32}$.765625
$\frac{51}{32}$.78125
$\frac{53}{32}$.796875
$\frac{55}{32}$.8125
$\frac{57}{32}$.828125
$\frac{59}{32}$.84375
$\frac{61}{32}$.859375
$\frac{63}{32}$.875
$\frac{15}{16}$.890625
$\frac{17}{16}$.90625
$\frac{19}{16}$.921875
$\frac{21}{16}$.9375
$\frac{23}{16}$.953125
$\frac{25}{16}$.96875
$\frac{27}{16}$.984375
$\frac{29}{16}$	1.

SECTION 6 – OPERATING WELDING GENERATOR – CC MODELS


6-1. Front Panel Controls For CC Models (See Section 6-2)




6-2. Description Of Front Panel Controls For CC Models (See Section 6-1)

Engine Starting Controls							
1 Magnetic Shutdown Switch Use switch during start-up to bypass engine shutdown system. System stops engine if oil pressure is too low or engine temperature is too high.				5 Engine Temperature Light Light goes on and engine stops if engine oil temperature is above 266 ° F (130° C).			
▲ Stop engine and fix trouble if Engine Temperature light goes on.							
2 Starting Aid Switch (Optional) Use switch to energize starting aid for cold weather starting.				6 Engine Oil Pressure Light Light goes on and engine stops if oil pressure is below 22 psi (150 kPa). Light goes on momentarily during start-up but goes out when engine reaches normal oil pressure.			
▲ Stop engine and fix trouble if Engine Oil Pressure light stays on after start-up.				7 Fuel Light Fuel light is not active on this model.			
3 Engine Control Switch Use switch to start engine, select engine speed (if unit has auto idle option), and stop engine. In Run position, engine runs at weld/power speed. In Run/Idle position (optional), engine runs at idle speed at no load and weld speed with load applied.				8 Engine Hour Meter			
To Start:				Engine Gauges			
☞ If engine does not start, let engine come to a complete stop before attempting restart.				☞ To read gauges and engine indicator lights with engine off, turn Engine Control switch to Run/Idle and press Magnetic Shutdown switch (see Section 11-1).			
Above 32° F (0° C): turn Engine Control switch to Start while pressing Shutdown switch. Release Engine Control switch when engine starts. Continue holding Shutdown switch until engine indicator lights go out.				9 Fuel Gauge Use gauge to check fuel level.			
Below 32° F (0° C) using optional starting aid switch:				To check fuel level when engine is not running, turn Engine Control switch to Run/Idle position and press Magnetic Shutdown switch.			
Deutz F4L2011-powered units – Turn Engine Control switch to Run/Idle position. Push Starting Aid switch up for 60 seconds. While still holding Starting Aid switch, press Magnetic Shutdown switch and turn Engine Control switch to Start. Release Engine Control switch and Starting Aid switch when engine starts. Continue holding Shutdown switch until engine indicator lights go out.				10 Battery Voltmeter (Optional) Use gauge to check battery voltage and monitor the engine charging system. The meter should read about 14 volts dc when the engine is running, and about 12 volts dc when the engine is stopped.			
Deutz F3L912-powered units – Press Magnetic Shutdown switch and turn Engine Control switch to Start. While cranking engine, push Starting Aid switch up and release. Release Engine Control switch when engine starts. Continue holding Shutdown switch until engine indicator lights go out.				11 Engine Temperature Gauge (Optional) Normal temperature is 212 - 239° F (100 - 115° C). If equipped with gauge option, engine stops if temperature exceeds 270° F (132° C).			
To Stop: turn Engine Control switch to Off position.				12 Engine Oil Pressure Gauge (Optional) Normal pressure is 30 – 60 psi (206 – 414 kPa). If equipped with gauge option, engine stops if pressure is below 20 psi (138 kPa).			
Engine Indicator Lights				Weld Controls			
4 Battery Charging Light Light goes on if engine alternator is not charging battery. Engine continues to run.				☞ Max OCV Control Circuit: This unit has a max OCV control circuit that resets Amperage Adjust control R1 to maximum when the arc breaks. When an arc is struck, weld output control returns to the R1 front panel or combination front panel/remote control setting. The Amperage Adjust control adjusts amperage only when welding and does not adjust open-circuit voltage.			
▲ Stop engine and fix trouble if Battery Charging light goes on.				<i>The max OCV circuit is disabled when the Stick/TIG Selection switch is in Scratch Start TIG position (see item 15).</i>			

6-3. Remote Amperage Control On CC Models (Optional)




6-4. Weld Control/Arc Condition Information Label



Notes

SECTION 7 – OPERATING WELDING GENERATOR – CC/CV MODELS

7-1. Front Panel Controls For CC/CV Models (See Section 7-2)



7-2. Description Of Front Panel Controls For CC/CV Models (See Section 7-1)



Engine Starting Controls

1 Magnetic Shutdown Switch

Use switch during start-up to bypass engine shutdown system. System stops engine if oil pressure is too low or engine temperature is too high.

2 Starting Aid Switch (Optional)

Use switch to energize starting aid for cold weather starting.

Deutz F4L2011-powered units use a glow plug starting aid. Push switch up for 60 seconds to operate the glow plug before cranking engine (see starting instructions following).

Deutz F3L912-powered units use an ether starting aid system. Push switch up and release while cranking engine to release ether (see starting instructions following).

3 Engine Control Switch

Use switch to start engine, select engine speed (if unit has auto idle option), and stop engine.

In Run position, engine runs at weld/power speed. In Run/Idle position (optional), engine runs at idle speed at no load and weld speed with load applied.

To Start:

If engine does not start, let engine come to a complete stop before attempting re-start.

Above 32° F (0° C): turn Engine Control switch to Start while pressing Shutdown switch. Release Engine Control switch when engine starts. Continue holding Shutdown switch until engine indicator lights go out.

Below 32° F (0° C) using optional starting aid switch:

Deutz F4L2011-powered units – Turn Engine Control switch to Run/Idle position. Push Starting Aid switch up for 60 seconds. While still holding Starting Aid switch, press Magnetic Shutdown switch and turn Engine Control switch to Start. Release Engine Control switch and Starting Aid switch when engine starts. Continue holding Shutdown switch until engine indicator lights go out.

Deutz F3L912-powered units – Press Magnetic Shutdown switch and turn Engine Control switch to Start. While cranking engine, push Starting Aid switch up and release. Release Engine Control switch when engine starts. Continue holding Shutdown switch until engine indicator lights go out.

To Stop: turn Engine Control switch to Off position.

Engine Indicator Lights

4 Battery Charging Light

Light goes on if engine alternator is not charging battery. Engine continues to run.

Stop engine and fix trouble if Battery Charging light goes on.

5 Engine Temperature Light

Light goes on and engine stops if engine oil temperature is above 266 ° F (130° C).

Stop engine and fix trouble if Engine Temperature light goes on.

6 Engine Oil Pressure Light

Light goes on and engine stops if oil pressure is below 22 psi (150 kPa). Light goes on momentarily during start-up but goes out when engine reaches normal oil pressure.

Stop engine and fix trouble if Engine Oil Pressure light stays on after start-up.

7 Fuel Light

Fuel light is not active on this model.

8 Engine Hour Meter

Engine Gauges

To read gauges and engine indicator lights with engine off, turn Engine Control switch to Run/Idle and press Magnetic Shutdown switch (see Section 11-1).

9 Fuel Gauge

Use gauge to check fuel level.

To check fuel level when engine is not running, turn Engine Control switch to Run/Idle position and press Magnetic Shutdown switch.

10 Battery Voltmeter (Optional)

Use gauge to check battery voltage and monitor the engine charging system. The meter should read about 14 volts dc when the engine is running, and about 12 volts dc when the engine is stopped.

11 Engine Temperature Gauge (Optional)

Normal temperature is 212 - 239° F (100 - 115° C). If equipped with gauge option, engine stops if temperature exceeds 270° F (132° C).

12 Engine Oil Pressure Gauge (Optional)

Normal pressure is 30 – 60 psi (206 – 414 kPa). If equipped with gauge option, engine stops if pressure is below 20 psi (138 kPa).

Weld Controls

13 Process/Contactor Switch

See Section 7-3 for Process/Contactor switch information.

14 Ampere Range Switch

Do not switch under load.

Use switch to select weld amperage range.

Use the lowest four ranges for Stick and TIG welding. Read the upper set of numbers at each range for Stick welding and the lower set at each range for TIG welding.

Use the highest range for MIG welding and for cutting and gouging (CAC-A).

For most welding applications, use lowest amperage range possible to help prevent arc outages.

15 Voltage/Amperage Adjust Control

With Process/Contactor switch in any Stick or TIG setting, use control to adjust amperage within range selected by Ampere Range switch. With Process/Contactor switch in any MIG position, use control to adjust voltage. With Voltage/Amperage Adjust Switch in Remote position, control limits the remote amperage in TIG mode, but has no effect in Stick and MIG modes.

Weld output would be about 223 A DC with controls set as shown (50% of 125 to 320 A).

The numbers around the control are for reference only and do not represent an actual percentage value.

16 Voltage/Amperage Adjust Switch And Remote 14 Receptacle

Use switch to select front panel or remote voltage/amperage control. For remote control, place switch in Remote position and connect remote control to Remote 14 receptacle RC14 (see Sections 5-13 and 7-4).

17 Polarity Switch (Optional)

Do not switch under load.

Use switch to change weld output. Select either DC Electrode Positive (DCEP) or DC Electrode Negative (DCEN).

Weld Meters


18 DC Voltmeter (Optional)

Voltmeter displays voltage at the weld output terminals, but not necessarily the welding arc due to resistance of cable and connections.

19 DC Ammeter (Optional)

Ammeter displays amperage output of the unit.

7-3. Process/Contactor Switch On CC/CV Models



1 Process/Contactor Switch

▲ Weld output terminals are energized when Process/Contactor switch is in an Electrode Hot position and the engine is running.

▲ DC voltage is still present at the weld terminals when Process/Contactor switch is in the Remote – Stick position and the engine is running.

Use switch to select weld process and weld output on/off control (see table below and Section 7-4).

Place switch in Remote positions to turn weld output on and off with a device connected to the remote 14 receptacle.

Place switch in Electrode Hot positions for weld output to be on whenever the engine is running.

Use Stick position for air carbon arc (CAC-A) cutting and gouging.

When switch is in a Stick position, the arc drive (dig) circuit provides additional amperage during low voltage (short arc length conditions) to prevent "sticking" electrodes.

The arc drive (dig) circuit is disabled when switch is in MIG or TIG positions.

Place switch in Electrode Hot - Stick position when using optional three-phase generator (see Section 7-4).


The engine auto idle option does not work in the Remote-TIG mode.

202 706


Process/Contactor Switch Settings

Switch Setting	Process	Output On/Off Control	Engine Auto Idle (Optional)
Remote – TIG	GTAW With HF Unit, Pulsing Device, Or Remote Control	At Remote 14 Receptacle	Not Active
Remote – Stick	Stick (SMAW) With Remote On/Off	At Remote 14 Receptacle	Active
Remote – MIG	MIG (GMAW)	At Remote 14 Receptacle	Active
Electrode Hot – MIG	MIG (GMAW)	Electrode Hot	Active
Electrode Hot – Stick	Stick (SMAW), Air Carbon Arc (CAC-A) Cutting And Gouging	Electrode Hot	Active
Electrode Hot – Scratch Start TIG	Scratch Start TIG (GTAW)	Electrode Hot	Active


7-4. Remote Voltage/Amperage Control On CC/CV Models (Optional)



Example: Combination Remote Amperage Control (Stick)




Example: Combination Remote Amperage Control (TIG)



SECTION 8 – OPERATING AUXILIARY EQUIPMENT


8-1. Generator Power Receptacles (Standard Models)



8-2. Connecting To Optional Three-Phase Generator (CC/CV Standard Models Only)



Single-Phase Power Connection



Place Process/Contactor switch in Electrode Hot - Stick position when using three-phase generator (see Section 7-3).

Single-Phase Generator Power


- 1 120/240 V 50 A Receptacle RC5

RC5 is connected to the optional three-phase generator and supplies 60 Hz single-phase power at weld/power speed. Maximum output from RC5 is 12 kVA/kW. Power available at RC5 is reduced when welding.

- 2 Circuit Breaker CB7


Circuit breaker CB7 protects single-phase receptacle RC5 and the load wires from overload. If CB7 opens, all three-phase generator output stops and the receptacle does not work.

Three-Phase Power Connection




AC \sim Output	Single Phase 1 \sim	Three Phase 3 \sim
Volts	120/240	240
Amps	50	48
KVA/KW	12	20
Frequency	60 Hz	
Engine Speed	1850 RPM	

Lead 42 connects to GROUND stud on front of unit.
Jumper 42 is connected to 90 at factory.



Rear Of Panel



Three-Phase Generator Power

- ▲ Stop engine.

- ▲ Power and weld outputs are live at the same time. Disconnect or insulate unused cables.

Have qualified person install according to circuit diagram and Generator Power Guidelines (see Section 14).

Remove generator power panel mounting screws. Tilt panel forward.

- 3 Lead 93
- 4 Lead 92
- 5 Lead 91
- 6 Lead 42 (Circuit Grounding Lead)
- 7 Lead 90 (Neutral)
- 8 Isolated Neutral Terminal
- 9 Jumper Lead 42
- 10 Grounding Terminal

Jumper 42 is connected to lead 90 at factory. Jumper 42 may be disconnected from neutral to meet applicable electrical codes.

Lead 42 connects to front panel Ground stud.

- 11 User-Supplied Leads
- 12 Circuit Breaker CB7 User Terminals

Connect user-supplied leads to terminals on CB7 and to the isolated neutral terminal and grounding terminal as necessary.


Circuit breaker CB7 protects single-phase receptacle RC5 and the load wires from overload. If CB7 opens, all three-phase generator output stops and the receptacle does not work.

Reinstall generator power panel.

8-3. Optional Generator Power Receptacles (Standard Models)



European Receptacle



120 V 20A 1~ 60 Hz 240 V 15 A

- 1 120 V 20 A AC GFCI Receptacle GFCI1
- 2 240 V 16 A AC European Receptacle RC1
- 3 240 V 15 A AC Australian Receptacle RC1
- 4 240 V 15 A AC South African Receptacle RC1

Receptacles supply 60 Hz single-phase power at weld/power speed.

If a ground fault is detected, the GFCI Reset button pops out and the receptacle does not work. Check for faulty tools plugged in receptacle. Press button to reset GFCI1.

At least once a month, run engine at weld/power speed and press test button to verify GFCI is working properly.

5 Circuit Breaker CB2
6 Circuit Breaker CB3
CB2 protects GFCI1 from overload. If CB2 opens, GFCI1 does not work. Press button to reset breaker.
CB3 protects RC1 from overload. If CB3 opens, RC1 does not work. Press button to reset breaker.

If a circuit breaker continues to open, contact Factory Authorized Service Agent.


Generator power is not affected by weld output.

Maximum output is 2.4 kVA/kW from GFCI1 and 4 kVA/kW from RC1. Maximum output from all receptacles is 4 kVA/kW.

EXAMPLE: If 13 A is drawn from RC1, only 7 A is available at GFCI1:


$$(240 V \times 13 A) + (120 V \times 7 A) = 4.0 \text{ kVA/kW}$$

Australian Receptacle




120 V 20A 1~ 60 Hz 240 V 15 A

South African Receptacle



120 V 20A 1~ 60 Hz 240 V 15 A

8-4. Generator Power Receptacles (CE Models)



Ref. 204 258

Generator power is not affected by weld output.

1 130 V 32 A AC Receptacle RC1

2 220 Volt 16 A AC Receptacle RC2

3 130 Volt 16 A AC Receptacle RC3

Receptacles supply 60 Hz single-phase power at weld/power speed.

4 Circuit Breaker CB1

5 Circuit Breakers CB2 And CB3

CB1 protects RC1 and the generator wind-

ing from overload. If CB1 opens, RC1 and RC2 do not work. Place switch in On position to reset breaker.

CB2 protects RC2, and CB3 protects RC3 from overload. If a circuit breaker opens, the receptacle does not work. Place switch in On position to reset breaker.

If a circuit breaker continues to open, contact Factory Authorized Service Agent.

Maximum output is 4 kVA/kW from RC1 and 2.2 kVA/kW from RC2 or RC3. Maximum output from all receptacles is 4 kVA/kW.

Combined output of receptacles is limited to 4 kVA/kW output of generator. If maximum output is exceeded, auxiliary equipment will stop or not run properly.

EXAMPLE: If 20 A is drawn from RC1, only 8 A is available at each of the other receptacles.

$$(110 \text{ V} \times 20 \text{ A}) + (110 \text{ V} \times 8 \text{ A}) + (110 \text{ V} \times 8 \text{ A}) = 4 \text{ kVA/kW.}$$

SECTION 9 – MAINTENANCE (DEUTZ F4L2011-POWERED UNITS)







Note

The oil/filter maintenance intervals are different for the Deutz F4L2011 and F3L912 engines (see maintenance schedules following).


Note

Follow the storage procedure in the engine owner's manual if the unit will not be used for an extended period.


9-1. Routine Maintenance (Deutz F4L2011-Powered Units)

      	<p>▲ Stop engine before maintaining. ☞ See Engine Manual and Maintenance Label for important start-up, service, and storage information. Service engine more frequently if used in severe conditions. * To be done by Factory Authorized Service Agent.</p>
<p> Every 8 h</p>	
 Wipe Up Spills.	  Check Fluid Levels. See Section 5-9.
 Drain Water From Fuel System. See Section 9-6.	
<p> Every 50 h</p>	
 Clean Air Filter. See Section 9-3.	  Clean And Tighten Weld Terminals.
<p> Every 100 h</p>	
 Clean Cooling System.	 Clean And Tighten Battery Connections.
 Check air cleaner hoses for cracks and loose clamps.	
<p> Every 250 h</p>	
  Replace Unreadable Labels.	 Check Belt Tension.
 Check And Clean Spark Arrestor. See Section 9-4.	
<p> Every 500 h</p>	
 Repair Or Replace Cracked Cables.	


 Every 1000 h




Change Oil. See
Section 9-6.




Change Oil Filter.
See Section 9-6.
Service more often
in dirty conditions.




Change Fuel
Filters. See
Section 9-6.




Service Welding
Generator Brushes
And Slip Rings.
Service More Often
In Dirty Conditions.*



Drain Sludge
From Fuel
Tank. See
Section 9-6.



Check
Valve
Clearance.*



Blow Out Or
Vacuum Inside.
During Heavy
Service,
Clean Monthly.

 Every 3000 h




Clean/Set
Injectors.*

Notes


9-2. Maintenance Label

DEUTZ F4L2011/F3L2011 AND F3L912 DIESEL ENGINES		250 h std.	3000 h std.	13 mm (1/2 in)	F3L912
F3L2011 MILLER 216 959 Deutz 117-9564 Gates AX44	F4L2011 MILLER 067 266 Deutz 117-9565 Gates 7435	F3L912 API: CD/CE/CF-4 F3L2011 F4L2011 8.2 L (8.7 qt) 8.5 L (9 qt)	F3L912 1000 h std. 500 h std. F3L2011 F4L2011 8.2 L (8.7 qt) 8.5 L (9 qt)	MILLER 066 271 Deutz 223-5256 Gates 7580	MILLER 066 271 Deutz 223-5256 Gates 7580
50 h std.	(Optional) MILLER 192 939 Donaldson P822769 WIX 46490	50 h std.	500 h std.	30 °C	30 °C
12 V BCI 24 650 A @ -18C (0F)	1250 RPM 1850 RPM	MILLER 192 938 Donaldson P822768 WIX 46489	MILLER 192 744 Donaldson P550587 Fram PH46	F3L912 MILLER 064 677 1.5L Opt. 066 212 1L Deutz 117-4418 1.5L Opt. 117-4417 1L Fram PH6923	F3L912 MILLER 064 677 1.5L Opt. 066 212 1L Deutz 117-4418 1.5L Opt. 117-4417 1L Fram P4102
8 h std.	250 h std.	1000 h std.	20° C (72° F)	2. F3L912	2. F3L912
DIN 51 601 BS 2869: A1, A2 ASTM D 975-81: 1-D, 2-D VV-F 800C: DF-A, DF-1, DF-2 $S \leq .5\%$	DIESEL 98.7 L (24.75 gal)	1. MILLER 192 744 Fram P145A	F3L912 In. - 0.3 mm (0.012 in) ex. - 0.5 mm (0.020 in)	MILLER 066 217 Deutz 117-4423 Donaldson P550345	MILLER 064 686 Deutz 117-4423 Fram P4102
			4500 h / 5 yr std.		
					F3/4L2011 Only
					215 233-B

9-3. Servicing Air Cleaner (Deutz F4L2011-Powered Units)






9-4. Inspecting/Cleaning Optional Spark Arrestor (Deutz F4L2011-Powered Units)




Notes


9-5. Adjusting Engine Speed (Deutz F4L2011-Powered Units)



Standard Models



Models With Automatic Idle (Optional)



Tools Needed:

3/8, 7/16 in

▲ Stop engine and let cool.

Engine speed is factory set and should not require adjustment. After tuning engine, check engine no load speed with a tachometer or frequency meter (see table for no load speeds). If necessary, adjust speed as follows:

Start engine and run until warm.

On CC Models, place Stick/TIG switch in Stick position.

On CC/CV models, turn Process/Contactor switch to Stick - Electrode Hot position.

Standard Models:

- 1 Engine Speed Adjustment Screw
- 2 Locking Nut

Loosen nut. Turn screw until engine runs at weld/power speed. Tighten nut.

Do not set engine speed higher than specified.

Models With Automatic Idle (Optional)

- 3 Throttle Rod
- 4 Locknut

Loosen locknuts. Place engine control switch in Run/Idle position.

Turn throttle rod until engine runs at idle speed. Tighten locknuts.

- 5 Engine Speed Adjustment Screw
- 6 Locknut

Place engine control switch in Run position.


Loosen locknut. Turn screw until engine runs at weld/power speed. Tighten locknut.

Do not set engine speed higher than specified.

▲ Stop engine.

Close door.

9-6. Servicing Fuel And Lubrication Systems (Deutz F4L2011-Powered Units)



▲ Stop engine and let cool.

▲ After servicing, start engine and check for fuel leaks. Stop engine, tighten connections as necessary, and wipe up spilled fuel.

- 1 Oil Filter
- 2 Oil Drain Valve And Hose
- 3 Oil Fill Cap
- 4 Primary Fuel Filter (Fuel/Water Separator)
- 5 Petcock
- 6 Secondary Fuel Filter
- 7 Fuel Tank Sludge Drain Valve

To change oil and filter:

Route oil drain hose and valve through hole in base. See engine manual and engine

maintenance label for oil/filter change information.

To drain water from fuel system:

Open primary fuel filter petcock and drain water into metal container. Close petcock when water-free fuel flows.

To replace primary fuel filter:

Turn filter counterclockwise. Remove filter.

Apply thin coat of fuel to gasket on new filter. Fill filter with fuel. Install filter and turn clockwise. Bleed air from fuel system according to engine manual.

Inspect fuel line, and replace if cracked or worn.

To replace secondary fuel filter:

Ref. 800 159-E / Ref. 802 170 / 802 313-A

See engine manual.

Close doors.

To drain sludge from fuel tank:

▲ Beware of fire. Do not smoke and keep sparks and flames away from drained fuel. Dispose of drained fuel in an environmentally-safe manner. Do not leave unit unattended while draining fuel tank.

▲ Properly lift unit and secure in a level position. Use adequate blocks or stands to support unit while draining fuel tank.

Attach 1/2 ID hose to drain valve. Put metal container under drain, and use screwdriver to open sludge drain valve. Close valve when sludge has drained. Remove hose.

9-7. Overload Protection (Deutz F4L2011-Powered Units)

! Warning:

Control Panel:

Front Panel Components:

Stop engine.

When a circuit breaker or fuse opens, it usually indicates a more serious problem exists. Contact Factory Authorized Service Agent.

1 Fuse F1
2 Fuse F2

F1 and F2 protect the stator exciter winding from overload. If F1 opens, weld and generator power is low or stops entirely. If F2 opens, weld output is low or stops entirely. 4 kVA/kW generator power is still available.

3 Circuit Breaker CB4 (Not Shown)
4 Circuit Breaker CB5 (CC/CV Models Only)
5 Circuit Breaker CB6 (CC/CV Models Only)
6 Circuit Breaker CB10 (Not Shown)
7 Circuit Breaker CB11
8 Circuit Breaker CB12
9 Circuit Breaker CB13
10 Circuit Breaker CB14 (Optional – Not Shown)

CB4 protects the welding arc drive (dig) circuit. If CB4 opens, electrode may stick to the workpiece more frequently during low voltage (short arc length) conditions. CB4 automatically resets when the fault is corrected.

CB5 protects the 24 volt ac output to remote receptacle RC14, and 24 volt output to field current regulator board PC1 (CC/CV models only). If CB5 opens, weld output and 24 volt output to RC14 stops. On units with optional three-phase generator, generator power output at receptacle RC5 also stops if CB5 opens.

CB6 protects the 115 volt ac output to remote receptacle RC14 (CC/CV models only). If CB6 opens, 115 volt output to RC14 stops.

CB10 protects the engine battery circuit. If CB10 opens, the engine will not crank. CB10 automatically resets when the fault is corrected.

CB11 protects the engine wiring harness. On CC models, if CB11 opens the max OCV circuit does not work and open circuit voltage is variable at all times (see max OCV note under Weld Controls in Section 6-2). If CB11 opens on CC/CV models, weld output stops (generator power is still available).

CB12 protects the field flashing circuit. If CB12 opens, the generator may not excite at start-up and weld and generator power output may not be available.

CB13 protects the engine shutdown circuit. If CB13 opens, the engine cranks but does not start.

CB14 protects the throttle solenoid on units with the auto idle option. If CB14 opens, the engine will not run at idle speed. CB14 automatically resets when the fault is corrected.





Press button to reset breaker.
 802 170-D / Ref. 802 311

SECTION 10 – MAINTENANCE (DEUTZ F3L912-POWERED UNITS)

Note


Follow the storage procedure in the engine owner's manual if the unit will not be used for an extended period.

10-1. Routine Maintenance (Deutz F3L912-Powered Units)


	<p>▲ Stop engine before maintaining.</p> <p> See Engine Manual and Maintenance Label for important start-up, service, and storage information. Service engine more frequently if used in severe conditions.</p> <p>* To be done by Factory Authorized Service Agent.</p>
 Every 8 h	
	Wipe Up Spills.
	Check Fluid Levels. See Section 5-9.
	Drain Water From Fuel System. See Section 10-7.
 Every 50 h	
	Clean Air Filter. See Section 10-3.
	Clean And Tighten Weld Terminals.
 Every 100 h	
	Clean Cooling System.
	Clean And Tighten Battery Connections.
	Check air cleaner hoses for cracks and loose clamps.
 Every 250 h	
	Replace Unreadable Labels.
	Check Belt Tension. 1/2 in. (13 mm)
	Check And Clean Spark Arrestor. See Section 10-4.




Every 500 h




Change Oil. See
Section 10-7.



Change Oil Filter.
See Section 10-7.
Service more often
in dirty conditions.




Check
Valve
Clearance.*




Repair Or
Replace
Cracked
Cables.




Every 1000 h




Change Fuel
Filters. See
Section 10-7.



Service Welding
Generator Brushes
And Slip Rings.
Service More Often
In Dirty Conditions.*




Drain Sludge
From Fuel
Tank. See
Section
10-7.



Blow Out Or
Vacuum Inside.
During Heavy
Service,
Clean Monthly.




Every 3000 h



Clean/Set
Injectors.*

Notes

10-2. Maintenance Label



10-3. Servicing Air Cleaner (Deutz F3L912-Powered Units)

▲ Stop engine.

▲ Do not run engine without air cleaner or with dirty element. Engine damage caused by using a damaged element is not covered by the warranty.

[] The air cleaner primary element can be cleaned but the dirt holding capacity of the filter is reduced with each cleaning. The chance of dirt reaching the clean side of the filter while cleaning and the possibility of filter damage makes cleaning a risk. Consider the risk of unwarrantable equipment damage when determining whether to clean or replace the primary element.

If you decide to clean the primary element, we strongly recommend installing an optional safety element to provide additional engine protection. **Never clean a safety element.** Replace the safety element after servicing the primary element three times.

Clean or replace primary element if dirty (see note above before cleaning). **Replace** primary element if damaged. Replace primary element yearly or after six cleanings.

1 Housing
 2 Safety Element (Optional)
 3 Primary Element
 4 Dust Cap
 5 Dust Ejector

To clean air filter:

Wipe off cap and housing. Remove cap and dump out dust. Remove element(s). Wipe dust from inside cap and housing with damp cloth. Reinstall safety element (if present). Reinstall cap.

▲ Do not clean housing with air hose.

Clean primary element with compressed air only.

Air pressure must not exceed 100 psi (690 kPa). Use 1/8 in (3 mm) nozzle and keep nozzle at least 2 in (51 mm) from inside of element. Replace primary element if it has holes or damaged gaskets.


Reinstall primary element and cap (dust ejector down).

Keep nozzle 2 in (51 mm) from element.

Blow Inspect


aircleaner1 9/00 – ST-153 929-B / ST-153 585 / Ref. S-0698-B

10-4. Inspecting/Cleaning Optional Spark Arrestor (Deutz F3L912-Powered Units)




Notes


10-5. Adjusting Engine Speed (Deutz F3L912-Powered Units)



10-6. Servicing Optional Ether Starting Aid (Deutz F3L912-Powered Units)



10-7. Servicing Fuel And Lubrication Systems (Deutz F3L912-Powered Units)



- ▲ Stop engine and let cool.
- ▲ After servicing, start engine and check for fuel leaks. Stop engine, tighten connections as necessary, and wipe up spilled fuel.

- 1 Oil Filter
- 2 Oil Drain Valve And Hose
- 3 Oil Fill Cap
- 4 Primary Fuel Filter (Fuel/Water Separator)
- 5 Petcock
- 6 Secondary Fuel Filter
- 7 Fuel Tank Sludge Drain Valve

To change oil and filter:

Route oil drain hose and valve through hole in base. See engine manual and engine

maintenance label for oil/filter change information.

To drain water from fuel system:

Open primary fuel filter petcock and drain water into metal container. Close petcock when water-free fuel flows.

To replace primary fuel filter:

Turn filter counterclockwise. Remove filter.

Apply thin coat of fuel to gasket on new filter. Fill filter with fuel. Install filter and turn clockwise. Bleed air from fuel system according to engine manual.

Inspect fuel line, and replace if cracked or worn.

To replace secondary fuel filter:

Ref. 800 159-E / Ref. 802 170 / 802 398

See engine manual.

Close doors.





To drain sludge from fuel tank:

▲ Beware of fire. Do not smoke and keep sparks and flames away from drained fuel. Dispose of drained fuel in an environmentally-safe manner. Do not leave unit unattended while draining fuel tank.

▲ Properly lift unit and secure in a level position. Use adequate blocks or stands to support unit while draining fuel tank.

Attach 1/2 ID hose to drain valve. Put metal container under drain, and use screwdriver to open sludge drain valve. Close valve when sludge has drained. Remove hose.

10-8. Overload Protection (Deutz F3L912-Powered Units)

▲ Stop engine.

When a circuit breaker or fuse opens, it usually indicates a more serious problem exists. Contact Factory Authorized Service Agent.

- 1 Fuse F1
- 2 Fuse F2

F1 and F2 protect the stator exciter winding from overload. If F1 opens, weld and generator power is low or stops entirely. If F2 opens, weld output is low or stops entirely. 4 kVA/kW generator power is still available.

- 3 Circuit Breaker CB4 (Not Shown)
- 4 Circuit Breaker CB5 (CC/CV Models Only)
- 5 Circuit Breaker CB6 (CC/CV Models Only)
- 6 Circuit Breaker CB10 (Not Shown)
- 7 Circuit Breaker CB11
- 8 Circuit Breaker CB12
- 9 Circuit Breaker CB13
- 9 Circuit Breaker CB14 (Not Shown)

CB4 protects the welding arc drive (dig) circuit. If CB4 opens, electrode may stick to the workpiece more frequently during low voltage (short arc length) conditions. CB4 automatically resets when the fault is corrected.

CB5 protects the 24 volt ac output to remote receptacle RC14, and 24 volt output to field current regulator board PC1 (CC/CV models only). If CB5 opens, weld output and 24 volt output to RC14 stops. On units with optional three-phase generator, power output at receptacle RC5 also stops if CB5 opens.

CB6 protects the 115 volt ac output to remote receptacle RC14 (CC/CV models only). If CB6 opens, 115 volt output to RC14 stops.

CB10 protects the engine battery circuit. If CB10 opens, the engine will not crank. CB10 automatically resets when the fault is corrected.

CB11 protects the engine wiring harness. On CC models, if CB11 opens the max OCV circuit does not work and open circuit voltage is variable at all times (see max OCV note under Weld Controls in Section 6-2). If CB11 opens on CC/CV models, weld output stops (generator power is still available).

CB12 protects the field flashing circuit. If CB12 opens, the generator may not excite at start-up and weld and generator power output may not be available.

CB13 protects the engine shutdown circuit. If CB13 opens, the engine cranks but does not start.

CB14 protects the engine fuel solenoid. If CB14 opens, the engine will not start. CB14 automatically resets when the fault is corrected.


Press button to reset breaker.

SECTION 11 – TROUBLESHOOTING


11-1. Diagnosing Causes Of Engine Fault Shutdowns



Pre-Start Diagnostic Checks



Turn Engine Control Switch To Run/Idle Position While Pressing Magnetic Shutdown Switch.



Use the front panel engine lights to help determine the cause of an automatic engine shutdown.

Correct the cause of the shutdown before operating the welding generator.

This unit does not have a battery charging fault shutdown. The engine continues to run if the Battery Charging Light goes on.

Normal Condition:
Oil Pressure Light On;
Battery Charging And Temperature Lights Off.

If Oil Pressure Light Is Off, See Factory Authorized Service Agent.

If Battery Charging Light Is On, Have Factory Authorized Service Agent Check Alternator.




If Temperature Light Is On, Correct Cause Of Overheating
(See Engine Manual).

If Engine Is Okay, See Factory Authorized Service Agent.

If Fault Continues, See Factory Authorized Service Agent.



Diagnostic Checks While Running



Start Engine (With No Load Applied).

Continue Pressing Shutdown Switch Until Engine Lights Go Off.


Normal Condition:
Engine Lights Go Off As Engine Reaches Normal Operating Condition.

Lights That Stay On After 20 Sec. Indicate Fault Condition.

Stop Engine And Correct Fault (See Above) If Fault Continues, See Factory Authorized Service Agent.

Ref. 202 705

11-2. Troubleshooting Tables



A. Welding – CC Models

Trouble	Remedy
No weld output; generator power output okay at ac receptacles.	<p>Check position of Ampere Range switch.</p> <p>Check position of optional polarity switch.</p> <p>Place Amperage Adjust switch in Panel position, or place switch in Remote position and connect remote control to Remote Amperage Adjust receptacle RC13 (see Sections 5-12 and 6-1).</p> <p>Check and secure connections to Remote Amperage Adjust receptacle RC13 (see Section 5-12).</p> <p>Check fuse F2, and replace if open (see Section 9-7). Have Factory Authorized Service Agent check integrated rectifier SR2 and the rotor.</p> <p>Have Factory Authorized Service Agent check brushes and slip rings, and field excitation circuit.</p>
No weld output or generator power output at ac receptacles.	<p>Disconnect equipment from generator power receptacles during start-up.</p> <p>Check fuses F1 and F2, and replace if open (see Section 9-7). Have Factory Authorized Service Agent check integrated rectifier SR1, capacitor C9, integrated rectifier SR2, and the rotor.</p> <p>Reset circuit breaker CB12. Have Factory Authorized Service Agent check diode D1 (see Section 9-7 or 10-8).</p> <p>Have Factory Authorized Service Agent check brushes and slip rings, and field excitation circuit.</p>
Erratic weld output.	<p>Check and tighten connections inside and outside unit.</p> <p>Be sure connection to work piece is clean and tight.</p> <p>Use dry, properly stored electrodes.</p> <p>Remove excessive coils from weld cables.</p> <p>Have Factory Authorized Service Agent check brushes and slip rings.</p>
High weld output.	<p>Check engine weld/power speed, and adjust if necessary (see Section 9-5 or 10-5).</p> <p>Have Factory Authorized Service Agent check OCV control circuit.</p>
Low weld output.	<p>Check engine weld/power speed, and adjust if necessary (see Section 9-5 or 10-5).</p> <p>Check fuses F1 and F2, and replace if open (see Section 9-7). Have Factory Authorized Service Agent check integrated rectifier SR1, capacitor C9, integrated rectifier SR2, and the rotor.</p>
Electrode sticks to the workpiece more frequently during low voltage (short arc length) conditions.	Circuit breaker CB4 may be open. CB4 automatically resets when the fault is corrected (see Section 9-7 or 10-8). Have Factory Authorized Service Agent check transformer T1 and integrated rectifiers SR4 and SR5.
Low open-circuit voltage.	Check engine weld/power speed, and adjust if necessary (see Section 9-5 or 10-5).
Maximum weld output only in each ampere range (with Stick/TIG Selection switch in Stick position).	Have Factory Authorized Service Agent check control relay CR7.
No remote fine amperage control.	<p>Place Amperage Adjust switch in correct position.</p> <p>Check and secure connections to Remote Amperage Adjust receptacle RC13 (see Section 5-12).</p> <p>Repair or replace remote control device.</p> <p>Reset circuit breaker CB11 (see Section 9-7). Have Factory Authorized Service Agent check control relay CR7.</p> <p>Have Factory Authorized Service Agent check OCV control circuit.</p> <p>Have Factory Authorized Service Agent check control relay CR7.</p>

B. Welding – CC/CV Models

Trouble	Remedy
No weld output; generator power output okay at ac receptacles.	<p>Place Process/Contactor switch in a Electrode Hot position, or place switch in a Remote position and connect remote contactor to optional Remote 14 receptacle RC14 (see Sections 5-13 and 7-1).</p> <p>Check position of Ampere Range switch.</p> <p>Check position of optional polarity switch.</p> <p>Reset circuit breaker CB11 (see Section 9-7 or 10-8).</p> <p>Reset circuit breaker CB5 (see Section 9-7 or 10-8). Check for faulty remote device connected to RC14.</p> <p>Check and secure connections to Remote 14 receptacle RC14 (see Section 5-13).</p> <p>Have Factory Authorized Service Agent check connector board PC6 and connections.</p> <p>Check fuse F2, and replace if open (see Section 9-7 or 10-8). Have Factory Authorized Service Agent check brushes and slip rings, field excitation circuit, field current regulator board PC1, and the rotor.</p>
No weld output or generator power output at ac receptacles.	<p>Disconnect equipment from generator power receptacles during start-up.</p> <p>Check fuses F1 and F2, and replace if open (see Section 9-7 or 10-8). Have Factory Authorized Service Agent check integrated rectifier SR1, capacitor C9, field current regulator board PC1, and the rotor.</p> <p>Have Factory Authorized Service Agent check brushes and slip rings, and field excitation circuit.</p>
Erratic weld output.	<p>Check and tighten connections inside and outside unit.</p> <p>Be sure connection to work piece is clean and tight.</p> <p>Use dry, properly stored electrodes.</p> <p>Remove excessive coils from weld cables.</p>
High weld output.	<p>Check position of Ampere Range switch and Voltage/Amperage Adjust control.</p> <p>Check engine weld/power speed, and adjust if necessary (see Section 9-5 or 10-5).</p> <p>Have Factory Authorized Service Agent check field current regulator board PC1.</p>
Voltage/Amperage control does not work when welding in Stick mode.	Place Ampere Range switch in lower range. Voltage/Amperage control does not work with Ampere Range switch in highest range.
Low weld output.	<p>Check engine weld/power speed, and adjust if necessary (see Section 9-5 or 10-5).</p> <p>Check fuses F1 and F2, and replace if open (see Section 9-7 or 10-8). Have Factory Authorized Service Agent check integrated rectifier SR1, capacitor C9, field current regulator board PC1, and the rotor.</p>
Electrode sticks to the workpiece more frequently during low voltage (short arc length) conditions.	Circuit breaker CB4 may be open. CB4 automatically resets when the fault is corrected (see Section 9-7 or 10-8). Have Factory Authorized Service Agent check transformer T1 and integrated rectifiers SR4 and SR5.
Low open-circuit voltage.	Check engine weld/power speed, and adjust if necessary.
No remote fine amperage or voltage control.	<p>Place Voltage/Amperage Adjust switch in Remote position.</p> <p>Check and secure connections to Remote 14 receptacle RC14 (see Section 5-13).</p> <p>Repair or replace remote control device.</p>
Constant speed wire feeder does not work.	<p>Reset circuit breaker CB5 or CB6 (see Section 9-7 or 10-8).</p> <p>Check and secure connections to Remote 14 receptacle RC14 (see Section 5-13).</p> <p>Repair or replace wire feeder.</p>
Low CV weld output.	Set Ampere Range switch to highest range.
Min or max CV weld output only.	<p>Check position of Voltage/Amperage Adjust control and Voltage/Amperage Adjust switch.</p> <p>Repair or replace remote control device.</p> <p>Have Factory Authorized Service Agent check field current regulator board PC1.</p>

C. Standard Generator Power

Trouble	Remedy
No generator power output at ac receptacles; weld output okay.	Reset receptacle circuit breakers.
No generator power or weld output.	Disconnect equipment from generator power receptacles during start-up.
	Check fuses F1 and F2, and replace if open (see Section 9-7 or 10-8). Have Factory Authorized Service Agent check integrated rectifier SR1, capacitor C9, and the rotor.
	Reset circuit breaker CB12. Have Factory Authorized Service Agent check diode D1 (CC models) or field current regulator board PC1 (CC/CV models) (see Section 9-7 or 10-8).
	Have Factory Authorized Service Agent check brushes and slip rings, and field excitation circuit.
High output at generator power ac receptacles.	Check engine weld/power speed, and adjust if necessary (see Section 9-5 or 10-5).
	Have Factory Authorized Service Agent adjust generator power field current resistor R3.
Low output at generator power ac receptacles.	Check engine weld/power speed, and adjust if necessary (see Section 9-5 or 10-5).
	Check fuse F1, and replace if open (see Section 9-7 or 10-8). Have Factory Authorized Service Agent check integrated rectifier SR1, resistor R3, and capacitor C9.

D. Optional Three-Phase Generator Power (CC/CV Models Only)

Trouble	Remedy
No or low output at optional three-phase generator/receptacle RC5.	Place Process/Contactor switch in Electrode Hot - Stick position (see Section 7-3).
	Reset circuit breaker CB7 (see Section 8-2).
	Reset circuit breaker CB5 (see Section 9-7 or 10-8).
	Check engine weld/power speed, and adjust if necessary (see Section 9-5 or 10-5).
	Have Factory Authorized Service Agent check brushes and slip rings, and field current regulator board PC1.
High output at optional three-phase generator/receptacle RC5.	Check engine weld/power speed, and adjust if necessary (see Section 9-5 or 10-5).
	Have Factory Authorized Service Agent check field current regulator board PC1.
Erratic output at optional three-phase generator/receptacle RC5.	Have Factory Authorized Service Agent check brushes and slip rings, and field current regulator board PC1.

E. Engine

Trouble	Remedy
Engine will not crank.	Check battery, and replace if necessary.
	Check battery connections and tighten if necessary.
	Circuit breaker CB10 may be open. CB10 automatically resets when fault is corrected (see Section 9-7 or 10-8). Have Factory Authorized Service Agent check engine wiring harness and components.
	Check engine wiring harness plug connections.
	Have Factory Authorized Service Agent check Engine Control switch S1.

Trouble	Remedy
Engine cranks but does not start.	Press Magnetic Shutdown switch MS1 when starting engine.
	Check fuel level.
	Reset circuit breaker CB13 (see Section 9-7 or 10-8). Have Factory Authorized Service Agent check engine wiring harness and components.
	Check battery and replace if necessary. Check engine charging system according to engine manual.
	On Deutz F3L912-powered units, allow circuit breaker CB14 to reset. Have Factory Authorized Service Agent check fuel solenoid FS1 (see Section 10-8).
	Have Factory Authorized Service Agent check control relay CR2, and fuel solenoid FS1.
Engine starts, but stops when Magnetic Shutdown switch is released.	Air in fuel system. See engine manual.
	When starting engine, continue holding Magnetic Shutdown switch until after engine indicator lights go out.
Engine hard to start in cold weather.	Check oil level. Automatic shutdown system stops engine if oil pressure is too low or engine temperature is too high (see Sections 5-9 and 11-1).
	Use optional starting aid switch (see Section 6-1 or 7-1).
	Keep battery in good condition. Store battery in warm area off cold surface.
	Use fuel formulated for cold weather (diesel fuel can gel in cold weather). Contact local fuel supplier for fuel information.
Engine suddenly stops.	Use correct grade oil for cold weather (see Section 9-2 or 10-2).
	Check fuel level.
	Check oil level. Automatic shutdown system stops engine if oil pressure is too low or engine temperature is too high (see Sections 5-9 and 11-1).
Engine slowly stopped and cannot be restarted.	See engine manual.
	Check fuel level.
	Check engine air and fuel filters (see Sections 9-3 and 9-6, or Sections 10-3 and 10-7).
Battery discharges between uses.	See engine manual.
	Turn Engine Control switch off when unit is not running.
	Clean top of battery with baking soda and water solution; rinse with clear water.
	Recharge or replace battery if necessary.
Engine idles, but does not come up to weld speed (models with idle option only).	Periodically recharge battery (approximately every 3 months).
	Have Factory Authorized Service Agent check idle module PC7.
	Check for obstructed throttle solenoid.
Engine does not run at idle speed (models with idle option only).	CC models: place Stick/TIG Selection switch in Stick position. CC/CV models: place Process/Contactor switch in any position but Remote-TIG.
	Check for obstructed throttle solenoid.
	Allow circuit breaker CB14 to reset. Have Factory Authorized Service Agent check throttle solenoid TS1 and linkage (see Section 9-7).
	Have Factory Authorized Service Agent check idle module PC7, control relays CR3 and CR6, and current transformer CT1.
Engine uses oil during run-in period; wetstacking occurs.	Dry engine (see Section 13).

Notes

MATERIAL THICKNESS REFERENCE CHART

	24 Gauge (.025 in)
	22 Gauge (.031 in)
	20 Gauge (.037 in)
	18 Gauge (.050 in)
	16 Gauge (.063 in)
	14 Gauge (.078 in)
	1/8 in (.125 in)
	3/16 in (.188 in)
	1/4 in (.25 in)
	5/16 in (.313 in)
	3/8 in (.375 in)
	1/2 in (.5 in)

SECTION 12 – ELECTRICAL DIAGRAMS










Figure 12-1. Circuit Diagram For CC Welding Generator (Non-CE Deutz F4L2011-Powered Units)



- Do not touch live electrical parts.
- Disconnect input power or stop engine before servicing.
- Do not operate with covers removed.
- Have only qualified persons install, use, or service this unit.



WITH THE ENGINE GAUGE OPTION,
THE OIL PRESSURE SENDER
REPLACES SWITCH S8.





Figure 12-2. Circuit Diagram For CC Welding Generator (CE Compliant Deutz F4L2011-Powered Units)



- Do not touch live electrical parts.
- Disconnect input power or stop engine before servicing.
- Do not operate with covers removed.
- Have only qualified persons install, use, or service this unit.








Figure 12-3. Circuit Diagram For CC/CV Welding Generator (Non-CE Deutz F4L2011-Powered Units)








Figure 12-4. Circuit Diagram For CC/CV Welding Generator (CE Compliant Deutz F4L2011-Powered Units)



- Do not touch live electrical parts.
- Disconnect input power or stop engine before servicing.
- Do not operate with covers removed.
- Have only qualified persons install, use, or service this unit.





- Do not touch live electrical parts.
- Disconnect input power or stop engine before servicing.
- Do not operate with covers removed.
- Have only qualified persons install, use, or service this unit.





Figure 12-5. Circuit Diagram For CC Welding Generator (Deutz F3L912-Powered Units)







Figure 12-6. Circuit Diagram For CC/CV Welding Generator (Deutz F3L912-Powered Units)

WARNING




- Do not touch live electrical parts.
- Disconnect input power or stop engine before servicing.
- Do not operate with covers removed.
- Have only qualified persons install, use, or service this unit.



SECTION 13 – RUN-IN PROCEDURE

13-1. Wetstacking



▲ Do not perform run-in procedure at less than 20 volts weld output and do not exceed duty cycle or equipment damage may occur.

1 Welding Generator

Run diesel engines near rated voltage and current during run-in period to properly seat piston rings and prevent wetstacking. See nameplate, rating label, or specifications section in this manual to find rated voltage and current.

☞ Do not idle engine longer than necessary. Piston rings seat faster if engine runs at weld/power rpm, and the welding generator is kept loaded during run-in.


2 Engine Exhaust Pipe

Wetstacking is unburned fuel and oil in the exhaust pipe and occurs during run-in if the engine is run too long at light load or idle rpm.

If exhaust pipe is coated with a wet, black, tar-like substance, dry the engine using one of the following run-in procedures.

See the engine manual for additional engine run-in information.

13-2. Run-In Procedure Using Load Bank



- ▲ Stop engine.
- ▲ Do not touch hot exhaust pipe, engine parts, or load bank/grid.
- ▲ Keep exhaust and pipe away from flammables.
- ▲ Do not perform run-in procedure at less than 20 volts weld output and do not exceed duty cycle or equipment damage may occur.

1 Load Bank

Turn all load bank switches Off. If needed, connect load bank to 115 volts ac wall receptacle or generator auxiliary power receptacle.

2 Welding Generator

Place A/V range switch in maximum position, A/V control in minimum position, and Output Selector switch (if present) in either DC position.

3 Weld Cables

Connect load bank to generator weld output terminals using proper size weld cables with correct connectors. Observe correct polarity.

Start engine and run for several minutes.

Set load bank switches and then adjust generator A/V control so load equals rated voltage and current of generator (see nameplate, rating label, or the specifications section in this manual).

Check generator and load bank meters after first five minutes then every fifteen minutes to be sure generator is loaded properly.

Check oil level frequently during run-in; add oil if needed.


After one hour (minimum) place A/V control in minimum position, then turn off load bank to remove load. Run engine several minutes at no load.

▲ Stop engine and let cool.

4 Engine Exhaust Pipe

Repeat procedure if wetstacking is present.

13-3. Run-In Procedure Using Resistance Grid



- ▲ Stop engine.
- ▲ Do not touch hot exhaust pipe, engine parts, or load bank/grid.
- ▲ Keep exhaust and pipe away from flammables.
- ▲ Do not perform run-in procedure at less than 20 volts weld output and do not exceed duty cycle or equipment damage may occur.

1 Resistance Grid
Use grid sized for generator rated output.

Turn Off grid.

2 Welding Generator

Place A/V range switch in maximum position, A/V control in minimum position, and Output Selector switch (if present) in either DC position.

3 Weld Cables

Connect grid to generator weld output terminals using proper size weld cables with correct connectors (polarity is not important).

4 Voltmeter

5 Clamp-On Ammeter

Connect voltmeter and ammeter as shown, if not provided on generator.

Start engine and run for several minutes.

Set grid switches and then adjust generator A/V control so load equals rated voltage and current of the generator (see nameplate, rating label, or the specifications section in this manual).

Check generator and meters after first five minutes then every fifteen minutes to be sure generator is loaded properly.

Check oil level frequently during run-in; add oil if needed.

After one hour (minimum), place A/V control in minimum position, then shut down grid to remove load. Run engine several minutes at no load.

▲ Stop engine and let cool.

6 Engine Exhaust Pipe

Repeat procedure if wetstacking is present.



SECTION 14 – GENERATOR POWER GUIDELINES

NOTE



The views in this section are intended to be representative of all engine-driven welding generators. Your unit may differ from those shown.

14-1. Selecting Equipment






Be sure equipment has this symbol and/or wording.

- 1 Generator Power Receptacles – Neutral Bonded To Frame
- 2 3-Prong Plug From Case Grounded Equipment
- 3 2-Prong Plug From Double Insulated Equipment

▲ Do not use 2-prong plug unless equipment is double insulated.

gen_pwr 11/02 – Ref. ST-159 730 / ST-800 577

14-2. Grounding Generator To Truck Or Trailer Frame



Electrically bond generator frame to vehicle frame by metal-to-metal contact.

▲ Always ground generator frame to vehicle frame to prevent electric shock and static electricity hazards.

1 Equipment Grounding Terminal (On Front Panel)

2 Grounding Cable (Not Supplied)

3 Metal Vehicle Frame


Connect cable from equipment ground terminal to metal vehicle frame. Use #10 AWG or larger insulated copper wire.

▲ If unit does not have GFCI receptacles, use GFCI-protected extension cord.


▲ Bed liners, shipping skids, and some running gear insulate the welding generator from the vehicle frame. Always connect a ground wire from the generator equipment grounding terminal to bare metal on the vehicle frame as shown.

S-0854

14-3. Grounding When Supplying Building Systems



14-4. How Much Power Does Equipment Require?



14-5. Approximate Power Requirements For Industrial Motors

Industrial Motors	Rating	Starting Watts	Running Watts
Split Phase	1/8 HP	800	300
	1/6 HP	1225	500
	1/4 HP	1600	600
	1/3 HP	2100	700
	1/2 HP	3175	875
Capacitor Start-Induction Run	1/3 HP	2020	720
	1/2 HP	3075	975
	3/4 HP	4500	1400
	1 HP	6100	1600
	1-1/2 HP	8200	2200
Capacitor Start-Capacitor Run	2 HP	10550	2850
	3 HP	15900	3900
	5 HP	23300	6800
	1-1/2 HP	8100	2000
	5 HP	23300	6000
Fan Duty	7-1/2 HP	35000	8000
	10 HP	46700	10700
	1/8 HP	1000	400
	1/6 HP	1400	550
	1/4 HP	1850	650
1/3 HP	2400	800	
	1/2 HP	3500	1100

14-6. Approximate Power Requirements For Farm/Home Equipment


Farm/Home Equipment	Rating	Starting Watts	Running Watts
Stock Tank De-Icer		1000	1000
Grain Cleaner	1/4 HP	1650	650
Portable Conveyor	1/2 HP	3400	1000
Grain Elevator	3/4 HP	4400	1400
Milk Cooler		2900	1100
Milker (Vacuum Pump)	2 HP	10500	2800
FARM DUTY MOTORS	1/3 HP	1720	720
Std. (e.g. Conveyors,	1/2 HP	2575	975
Feed Augers, Air	3/4 HP	4500	1400
Compressors)	1 HP	6100	1600
	1-1/2 HP	8200	2200
	2 HP	10550	2850
	3 HP	15900	3900
	5 HP	23300	6800
High Torque (e.g. Barn	1-1/2 HP	8100	2000
Cleaners, Silo Unloaders,	5 HP	23300	6000
Silo Hoists, Bunk Feeders)	7-1/2 HP	35000	8000
	10 HP	46700	10700
3-1/2 cu. ft. Mixer	1/2 HP	3300	1000
High Pressure 1.8 Gal/Min	500 PSI	3150	950
Washer 2 gal/min	550 PSI	4500	1400
2 gal/min	700 PSI	6100	1600
Refrigerator or Freezer		3100	800
Shallow Well Pump	1/3 HP	2150	750
	1/2 HP	3100	1000
Sump Pump	1/3 HP	2100	800
	1/2 HP	3200	1050

14-7. Approximate Power Requirements For Contractor Equipment

Contractor	Rating	Starting Watts	Running Watts
Hand Drill	1/4 in	350	350
	3/8 in	400	400
	1/2 in	600	600
Circular Saw	6-1/2 in	500	500
	7-1/4 in	900	900
	8-1/4 in	1400	1400
Table Saw	9 in	4500	1500
	10 in	6300	1800
Band Saw	14 in	2500	1100
Bench Grinder	6 in	1720	720
	8 in	3900	1400
	10 in	5200	1600
Air Compressor	1/2 HP	3000	1000
	1 HP	6000	1500
	1-1/2 HP	8200	2200
	2 HP	10500	2800
Electric Chain Saw	1-1/2 HP, 12 in	1100	1100
	2 HP, 14 in	1100	1100
Electric Trimmer	Standard 9 in	350	350
	Heavy Duty 12 in	500	500
Electric Cultivator	1/3 HP	2100	700
Elec. Hedge Trimmer	18 in	400	400
Flood Lights	HID	125	100
	Metal Halide	313	250
	Mercury	1000	
	Sodium	1400	
	Vapor	1250	1000
Submersible Pump	400 gph	600	200
Centrifugal Pump	900 gph	900	500
Floor Polisher	3/4 HP, 16 in	4500	1400
	1 HP, 20 in	6100	1600
High Pressure Washer	1/2 HP	3150	950
	3/4 HP	4500	1400
	1 HP	6100	1600
55 gal Drum Mixer	1/4 HP	1900	700
Wet & Dry Vac	1.7 HP	900	900
	2-1/2 HP	1300	1300

14-8. Power Required To Start Motor

AC MOTOR	
VOLTS	230
CODE	M
HP	1/4
AMPS	2.5
Hz	60
PHASE	1



Single-Phase Induction Motor Starting Requirements

Motor Start Code	G	H	J	K	L	M	N	P
KVA/HP	6.3	7.1	8.0	9.0	10.0	11.2	12.5	14.0

$$\frac{\text{kVA}/\text{HP} \times \text{HP} \times 1000}{\text{VOLTS}} = \text{STARTING AMPERAGE}$$

EXAMPLE: Calculate the starting amperage required for a 230 V, 1/4 HP motor with a motor start code of M.

Volts = 230 HP = 1/4 Using Table, Code M results in kVA/HP = 11.2

$$\frac{11.2 \times 1/4 \times 1000}{230} = 12.2 \text{ A} \quad \text{Starting the motor requires 12.2 amperes.}$$

S-0624

- 1 Motor Start Code
- 2 Running Amperage
- 3 Motor HP
- 4 Motor Voltage

To find starting amperage:


Step 1: Find code and use table to find kVA/HP. If code is not listed, multiply running amperage by six to find starting amperage.

Step 2: Find Motor HP and Volts.

Step 3: Determine starting amperage (see example).

Welding generator amperage output must be at least twice the motor's running amperage.

14-9. How Much Power Can Generator Supply?



- 1 Limit Load To 90% Of Generator Output

Always start non-resistive (motor) loads in order from largest to smallest, and add resistive loads last.

- 2 5 Second Rule


If motor does not start within 5 seconds, turn off power to prevent motor damage. Motor requires more power than generator can supply.

Ref. ST-800 396-A / S-0625

14-10. Typical Connections To Supply Standby Power



▲ Properly install and ground this equipment according to its Owner's Manual and national, state, and local codes.



```
graph LR; 1[1 Utility Electrical Service] --> 2[2 Transfer Switch]; 2 --> 3[3 Fused Disconnect Switch<br>(If Required)]; 3 --> 4[4 Welding Generator Output]; 4 --> 5[5 Essential Loads];
```

▲ Have only qualified persons perform these connections according to all applicable codes and safety practices.

▲ Properly install and ground this equipment according to its Owner's Manual and national, state, and local codes.

Customer-supplied equipment is required if generator will supply standby power during emergencies or power outages.


1 Utility Electrical Service
2 Transfer Switch (Double-Throw)

3 Fused Disconnect Switch
Install correct switch (customer-supplied) if required by electrical code.

4 Welding Generator Output
Generator output voltage and wiring must be consistent with regular (utility) system voltage and wiring.

5 Essential Loads
Connect generator with temporary or permanent wiring suitable for the installation.
Turn off or unplug all equipment connected to generator before starting or stopping engine. When starting or stopping, the engine has low speed which causes low voltage and frequency.

Notes



Work like a Pro!

Pros weld and cut safely. Read the safety rules at the beginning of this manual.

14-11. Selecting Extension Cord (Use Shortest Cord Possible)



Cord Lengths for 120 Volt Loads

▲ If unit does not have GFCI receptacles, use GFCI-protected extension cord.

Current (Amperes)	Load (Watts)	Maximum Allowable Cord Length in ft (m) for Conductor Size (AWG)*					
		4	6	8	10	12	14
5	600			350 (106)	225 (68)	137 (42)	100 (30)
7	840		400 (122)	250 (76)	150 (46)	100 (30)	62 (19)
10	1200	400 (122)	275 (84)	175 (53)	112 (34)	62 (19)	50 (15)
15	1800	300 (91)	175 (53)	112 (34)	75 (23)	37 (11)	30 (9)
20	2400	225 (68)	137 (42)	87 (26)	50 (15)	30 (9)	
25	3000	175 (53)	112 (34)	62 (19)	37 (11)		
30	3600	150 (46)	87 (26)	50 (15)	37 (11)		
35	4200	125 (38)	75 (23)	50 (15)			
40	4800	112 (34)	62 (19)	37 (11)			
45	5400	100 (30)	62 (19)				
50	6000	87 (26)	50 (15)				

*Conductor size is based on maximum 2% voltage drop

Cord Lengths for 240 Volt Loads

▲ If unit does not have GFCI receptacles, use GFCI-protected extension cord.


Current (Amperes)	Load (Watts)	Maximum Allowable Cord Length in ft (m) for Conductor Size (AWG)*					
		4	6	8	10	12	14
5	1200			700 (213)	450 (137)	225 (84)	200 (61)
7	1680		800 (244)	500 (152)	300 (91)	200 (61)	125 (38)
10	2400	800 (244)	550 (168)	350 (107)	225 (69)	125 (38)	100 (31)
15	3600	600 (183)	350 (107)	225 (69)	150 (46)	75 (23)	60 (18)
20	4800	450 (137)	275 (84)	175 (53)	100 (31)	60 (18)	
25	6000	350 (107)	225 (69)	125 (38)	75 (23)		
30	7000	300 (91)	175 (53)	100 (31)	75 (23)		
35	8400	250 (76)	150 (46)	100 (31)			
40	9600	225 (69)	125 (38)	75 (23)			
45	10,800	200 (61)	125 (38)				
50	12,000	175 (53)	100 (31)				

*Conductor size is based on maximum 2% voltage drop

SECTION 15 – PARTS LIST

Hardware is common and not available unless listed.

A Deutz F4L2011 engine-powered unit is shown below. See insert for parts specific to a Deutz F3L912-powered unit. Parts not related to the engines are the same in both units.




CC CC Models Only

CV CC/CV Models Only

Figure 15-1. Main Assembly

A Deutz F4L2011 engine-powered unit is shown below. See insert for parts specific to a Deutz F3L912-powered unit. Parts not related to the engines are the same in both units.

Deutz F3L912 Engine



Item No.	Dia. Mkgs.	Part No.	Description	Quantity
Figure 15-1. Main Assembly				
... 1		189 824 ..	PANEL, gen LH	1
... 1		◆199 294 ..	PANEL, gen LH ss	1
... 2		191 623 ..	LABEL, warning all panels must be in place while running	2
... 2		176 106 ..	LABEL, warning moving parts (Wordless Label)	2
... 3		+189 828 ..	PANEL, engine side	1
... 3		◆+199 301 ..	PANEL, engine side ss	1
		◆212 570 ..	Baffle, engine side (CE Rated)	1
... 4	Z1	189 395 ..	REACTOR, ac	1
... 4	Z1	◆201 520 ..	REACTOR, ac environmental	1
... 5	1T	038 621 ..	BLOCK, term 30A 4 pole frict term str	1
		038 620 ..	LINK, jumper term blk 30A	2
... 6		081 499 ..	BRACKET, mtg strip terminal	1
... 7		206 352 ..	BRACE, front to center upright	2
... 8	SR4, SR5	035 704 ..	RECTIFIER, integ bridge 40. amp 800v	2
... 9	CB4	045 061 ..	CIRCUIT BREAKER, auto reset 24vdc 7 amp	1
... 10		201 697 ..	PAN, reactor and rectifier	1
... 11	T1	201 613 ..	TRANSFORMER w/bracket	1
... 11	T1	◆205 636 ..	TRANSFORMER w/bracket (environmental coating)	1
... 12		173 352 ..	EXTRUSION, rubber clamp/bulb (order by ft)	3ft
... 13		189 708 ..	FIREWALL, top	1
... 14		191 307 ..	COVER, plate	1
... 15		191 829 ..	HOSE, air cleaner	1
... 16		189 763 ..	BRACKET, mtg air cleaner	1
... 17		189 764 ..	AIR CLEANER, intake	1
		*192 938 ..	FILTER, air element primary	1
		*◆192 939 ..	FILTER, air element safety	1
... 18		189 464 ..	SEAL, weather lift eye	1
		173 909 ..	HOSE, sae .312 id x .560 od x 24.000 (order by ft)	2
... 19		201 658 ..	UPRIGHT, center assembly	1
... 20		+200 999 ..	BASE	1
... 20		◆+203 382 ..	BASE e-coat	1
... 21		196 220 ..	BRACKET, hold down fuel tank rear	1
... 22		192 362 ..	BRACKET, mtg nyl 1/2 conduit	1
... 23		+201 934 ..	COVER, top	1
... 23		◆+202 640 ..	COVER, top ss	1
... 24		189 052 ..	GROMMET, plastic neck filler fuel	1
... 25		190 198 ..	CAP, tank screw-on 3.500 in w/vent	1
... 26		192 041 ..	LABEL, use diesel fuel only	1
... 26		176 103 ..	LABEL, use diesel fuel only (Wordless Label)	1
... 27		108 487 ..	LABEL, warning falling equipment	2
... 27		176 104 ..	LABEL, warning falling equipment (Wordless Label)	2
... 28		176 230 ..	LABEL, warning hot exhaust	1
... 29		105 734 ..	PIPE, muffler extension elbow 1.875 OD	1
... 29		201 592 ..	PIPE, exhaust (CE Rated)	1
... 30		201 851 ..	COVER, radiator access	1
... 31		191 354 ..	SUPPORT, cover	1
... 31		202 633 ..	SUPPORT, cover e-coat	1
... 32		010 875 ..	CLAMP, muffler 2.000 dia u pld	1
... 33		200 730 ..	MANIFOLD, exhaust muffler	1
... 34		Figure 15-6 ..	GENERATOR	1
... 35		013 367 ..	LABEL, warning moving parts	2
... 35		176 106 ..	LABEL, warning moving parts (Deutz F4L2011) (Wordless Label)	2
... 36		191 577 ..	GUARD, starter (Deutz F4L2011 engine)	1
... 37		191 809 ..	BRACKET, mtg engine LH (Deutz F4L2011 engine)	1
... 38		190 951 ..	EDGE TRIM, styel tl750-b2 x 1/16 black w/clips 1.625	1
... 39		191 817 ..	BAFFLE, air (Deutz F4L2011 engine)	1

Item No.	Dia. Mkgs.	Part No.	Description	Quantity
Figure 15-1. Main Assembly (Continued)				
... 40		213 877 ..	ENGINE, Deutz dsl elec F4L2011 (consisting of)	1
		*067 265 ..	FILTER, oil (engine) (Deutz F4L2011 engine)	1
		*192 744 ..	FILTER, fuel spin-on (Deutz F4L2011 engine)	1
		*066 217 ..	FILTER, fuel secondary (Deutz F4L2011 engine)	1
		*195 745 ..	SWITCH, oil pressure	1
		*195 746 ..	SENDER, coolant	1
		◆ 174 064 ..	IDLE, solenoid assy	1
		◆ 175 937 ..	BRACKET, support solenoid	1
... 41		*067 266 ..	BELT, blower (Deutz F4L2011 engine)	1
... 42		201 714 ..	BOX, air intake (Deutz F4L2011 engine)	1
... 43		201 748 ..	UPRIGHT, rear	1
... 43		◆ 202 638 ..	UPRIGHT, rear ss	1
... 44		190 206 ..	CABLE, bat neg 42 in lg No. 2 awg w/clamp and .375rng	1
... 45		108 081 ..	TERMINAL PROTECTOR, battery post mtg	2
... 46		190 207 ..	CABLE, bat pos 45 in lg No. 1 awg w/clamp and .406rng	1
... 47		203 430 ..	BRACKET, battery holddown	1
... 48		190 897 ..	BATTERY, stor 12V 650crk 110rsv gp 24	1
... 49		201 006 ..	BOLT, j stl .312-18 x 8.500 pld	2
... 50		+201 183 ..	COVER, battery access	1
... 50		202 639 ..	COVER, battery access ss	1
... 51		168 385 ..	LABEL, warning battery explosion can blind	1
... 51		176 108 ..	LABEL, warning battery explosion can blind (Wordless Label)	1
... 52		147 923 ..	LABEL, warning moving parts can cause serious injury	1
... 52		176 106 ..	LABEL, warning moving parts (Wordless Label)	1
... 53		+215 252 ..	GUARD, belt	1
... 54		147 923 ..	LABEL, warning moving parts can cause serious injury	3
... 55		199 849 ..	SCREW, 625-11 x 4.00hexhd pln gr 5 pld	4
... 56		071 731 ..	WASHER, flat .656 ID x 2.250 OD x .187T stl pld	4
... 57		191 812 ..	BRACKET, mtg engine RH (Deutz F4L2011 engine)	1
... 58		071 890 ..	RETAINER, mount eng/gen	4
... 59		071 730 ..	TUBING, stl .875 OD x 12ga wall x 2.500	4
... 60		083 476 ..	MOUNT, eng/gen nprn .875 ID x 2.500 OD x 2.000	4
... 61		135 205 ..	NUT, 625-11 .94hex .76H stl pld elastic stop nut	4
		199 507 ..	HOSE, oil drain assy 20 in (consisting of)	1
... 62		165 271 ..	VALVE, oil drain 3/8-18NPTF	1
... 63		176 529 ..	FITTING, hose brs barbed fem 1/2tbg x 3/8NPT	1
... 64		113 854 ..	HOSE, SAE .500 ID x .780 OD xc oil (order by ft)	2ft
... 65		176 528 ..	FITTING, hose brs barbed elbow fem 1/2 tbg x 1/2 NPT	1
... 66		173 336 ..	FITTING, adapter oil drain	1
... 67			WASHER, oil drain (available through engine manufacturer)	1
... 68		191 816 ..	BRACKET, mtg fuel filter/solenoid (Deutz F4L2011 engine)	1
... 69		192 750 ..	BASE, fuel filter w/adapter	1
		192 741 ..	BLOCK, spacer mtg filter base	1
... 70		145 282 ..	FITTING, hose brs barbed elbow M 5/16tbg x 1/4NPT	2
... 71		107 816 ..	HOSE, SAE .250 ID x .500 OD xc oil (order by ft)	3ft
		134 835 ..	HOSE, SAE .312 ID X .560 OD X 31.000 (order by ft)	4.5ft
... 72		*192 744 ..	FILTER, fuel spin-on	1
... 73		190 992 ..	KEEPER, latch engine access door	1
... 74		190 076 ..	CHANNEL, stiffener engine access	1
... 74		◆ 202 635 ..	CHANNEL, stiffener engine access e-coat	1
... 75		199 592 ..	LATCH, paddle series 20 (black)	1
... 76		200 444 ..	LABEL, diesel engine maintenance Deutz (Wordless Label)	1
... 77		+200 989 ..	DOOR, engine access	1
... 77		+210 736 ..	DOOR, engine access ss	1
... 78		189 975 ..	HINGE, door access 180deg	2
... 79		208 141 ..	STOP, door	2
... 80		189 826 ..	PANEL, rocker	1

Item No.	Dia. Mkgs.	Part No.	Description	Quantity
Figure 15-1. Main Assembly (Continued)				
... 80	199 298 ..	PANEL, rocker ss		1
... 81	189 827 ..	PANEL, gen RH		1
... 81	199 300 ..	PANEL, gen RH ss		1
... 82	191 626 ..	BUMPER, door engine access		2
... 83	189 245 ..	TANK, fuel 23gal (consisting of)		1
... 84	124 253 ..	BUSHING, tank fuel		4
	084 173 ..	CLAMP, hose .460 - .545clp dia slftng		2
... 85	189 912 ..	FITTING, stl barbed elbow w/.047 in orf zinc pld		1
... 86	189 909 ..	FITTING, stand pipe hose .250 x 9.260 lg 90deg zinc		1
... 87	189 913 ..	FITTING, stl barbed elbow zinc pld		1
... 88	190 142 ..	SENDER, fuel gauge 9.7500 deep tank		1
... 89	189 910 ..	FITTING, stand pipe hose .3125 x 9.260 lg 90deg zinc		1
... 90	189 908 ..	VALVE, drain fuel 180deg		1
... 91	181 572 ..	BUSHING, tank fuel		1
... 92	191 446 ..	EXTRUSION, rubber w/adhesive 1.000 x 1.000 D (order by ft)		6ft
... 93	191 897 ..	BRACKET, mtg unit		4
... 94	191 512 ..	BRACKET, hold down fuel tank		1
... 95	190 250 ..	LABEL, warning do not weld on base		2
... 95	200 864 ..	LABEL, warning do not weld on base (Wordless Label)		2
... 96	190 179 ..	PANEL, mtg components		1
... 97	R4 .. c _v 191 292 ..	RESISTOR, WW fxd 375W 50 ohm w/mtg bkt		1
... 98	R2 .. 189 699 ..	RESISTOR, WW tap 375W 10 ohm w/mtg bkt		1
... 99	R3 .. c _v 189 699 ..	RESISTOR, WW tap 375W 10 ohm w/mtg bkt		1
... 100	Figure 15-2, Figure 15-3	CONTROL BOX ASSEMBLY		1
... 101	189 731 ..	FIREWALL, lower		1
... 102	Figure 15-7 ..	MAIN RECTIFIER ASSEMBLY		1
... 103	191 448 ..	TOP, cover front upright		1
... 103	♦199 305 ..	TOP, cover front upright ss		1
... 104	+201 750 ..	UPRIGHT, front		1
... 104	♦+202 637 ..	UPRIGHT, front ss		1
... 105	134 792 ..	LABEL, warning general precautionary		1
... 105	176 105 ..	LABEL, warning general precautionary (Wordless Label)		1
... 106	Figure 15-4, Figure 15-5	PANEL, front w/components		1
... 107	♦202130 ..	XFMR, current sensing		1
... 108	c _v 193 453 ..	BRACKET, mtg box fcr		1
... 109	PC1 .. c _v 189 143 ..	MODULE, field current regulator		1
	190 058 ..	NUT, .250-20 u-nut multi-thread		19
	049 525 ..	NUT, 312-18 u-nut multi-thread		32
	202 031 ..	KIT, label (includes safety and informational labels)		1
	201 062 ..	KIT, label (includes safety and informational labels) (Wordless Labels) ..		1
... 110	199 063 ..	ENGINE, Deutz dsl elec F3L912 d0392-166/00		1
... 111	*064 677 ..	FILTER, oil (Deutz F3L912 engine)		1
... 112	*066 271 ..	BELT, blower (Deutz F3L912 engine)		1
... 113	*195 745 ..	SWITCH, pressure oil 1.5 bar nc cont		1
... 114	*195 746 ..	SENDER, coolant temp & 130 degee C switch		1
... 115	194 135 ..	BACKPLATE, Deutz F3L912 engine		1
... 116	194 572 ..	SUPPORT, front engine (Deutz F3L912 engine)		1
... 117	FS1 .. 141 346 ..	SHUTDOWN KIT, engine (Deutz F3L912 engine)		1
... 118	118 452 ..	FTG, adapter oil drain (Deutz F3L912 engine)		1
... 119	193 313 ..	MANIFOLD, exhaust muffler (Deutz F3L912 engine)		1
... 120	194 496 ..	BAFFLE, lower air outlet (Deutz F3L912 engine)		1
... 121	194 497 ..	BAFFLE, upper air outlet (Deutz F3L912 engine)		1
... 122	194 500 ..	BAFFLE, air intake (Deutz F3L912 engine)		1
... 123	194 485 ..	HOSE, air cleaner (Deutz F3L912 engine)		1
... 124	+201 714 ..	BOX, air intake (Deutz F3L912 engine)		1

Item No.	Dia. Mkgs.	Part No.	Description	Quantity
----------	---------------	----------	-------------	----------

Figure 15-1. Main Assembly (Continued)

... 125	195 560 ..	GUARD, starter hole (Deutz F3L912 engine)	1
... 126	194 467 ..	WASHER, flat 6.25idx11.50odx.062t buna n	1
... 127	212 944 ..	LABEL, cc stick overlap weld ranges	1

+ When ordering a component originally displaying a precautionary label, the label should also be ordered. Order label individually or as part of Label Kit 202 031 or Label Kit 201 062 (Wordless Labels).


* Recommended Spare Parts.

c_C CC models only.

c_V CC/CV models only.

◆ optional

To maintain the factory original performance of your equipment, use only Manufacturer's Suggested Replacement Parts. Model and serial number required when ordering parts from your local distributor.



802 551-E

Figure 15-2. Control Box Assembly – CC Models

Item No.	Dia. Mkgs.	Part No.	Description	Quantity
----------	---------------	----------	-------------	----------

Figure 15-2. Control Box Assembly – CC Models (Figure 15-1 Item 100)


... 1 ...	F1, F2 ...	*085 874 ..	FUSE, mintr cer slo-blo 10A 250V	2
... 2	046 432 ..	HOLDER, fuse mintr .250 x 1.250	2	
... 3	201 077 ..	CONTROL BOX, lh	1	
... 4	201 078 ..	CONTROL BOX, rh	1	
... 5	201 079 ..	COVER, control box	1	
... 6	C12 ...	191 944 ..	CAPACITOR, polyp met film 10. uf 250 vac 10%	1

Item No.	Dia. Mkgs.	Part No.	Description	Quantity
Figure 15-2. Control Box Assembly – CC Models (Continued)				
.....	201 681	.. HARNESS, control box, weld control (consisting of)	1
.... 7	CR7	188 636 RELAY, OCV control	1
.... 8	R8	214 863 RESISTOR BOARD	1
.... 9	SR1, SR2	035 704 RECTIFIER, integ 40A 800V	2
.... 10	CR5	090 104 RELAY, encl 12VDC SPST 30A/15VDC	1
.....	S5	011 609 SWITCH, tgl spdt 15a 125vac on–none–on spd term chr (located on front panel, see Figure 15-4)	1
.....	S6	011 622 SWITCH, tgl 3pdt 15a 125vac on–none–on spd term (located on front panel, see Figure 15-4)	1
.....	RC4	047 483 CONNECTOR, rect univ 084 15P/S 3 row rcpt cable/panel lkg	1
.....	RC3	158 466 CONNECTOR, rect univ 084 12P/S 3 row rcpt cable/panel lkg	1
.....	RC1	135 133 CONNECTOR, rect univ 084 9P/S 3 row rcpt cable/panel lkg	1
.....	148 850	SOCKET, relay 5 pin	1
.....	177 859	CONN, body 5 terminal (to engine control switch S1)	1
.....	150 316	CONN, rect univ 039 6p/s 3row plug cable lkg	6
.....	092 670	CONN, rect univ 084 3p/s 1row plug cable lkg	1
.... 11	CB11, 12, 13	139 266 CIRCUIT BREAKER, man reset 1P 15A 250VAC frict	3
.....	190 260	.. HARNESS, unit weld control (consisting of)	1
.....	PLG3	158 465 CONN, rect univ 084 12p/s 3row plug cable lkg	1
.....	187 654	SEAL, wire univ 12p/s 3row	1
.....	PLG6	114 063 CONN, rect univ 084 4p/s 1row plug cable lkg	1
.....	192 309	CLIP, snap in .630 bundle .250 hole .248 thk	2
.... 12	177 136 CLAMP, capacitor 1.375dia	1
.... 13	C9	087 110 CAPACITOR, elctlt 240uf 200VDC	1
.... 14	R6	141 424 RESISTOR, ww fxd 30 w 25 ohm faston te	1
.... 15	PC7	◆ 195 706 MODULE, pull to idle, two output, 7 pin	1
.... 16	CR4	◆ 113 247 RELAY, encl 12vdc dpdt 20a/120vac 8pin flange mtg	1
.... 17	CR6	◆ 090104 RELAY, encl 12vdc spst 30a/15vdc 5pin flange mtg	1
.... 18	CR2, CR3	090 104 RELAY, encl 12VDC SPST 30A/15VDC spin flange mtg	2
.....	206 024	.. HARNESS, engine control (Deutz F4L2011 engine) (consisting of)	1
.... 19	D1/C1	189 701 DIODE/CAPACITOR BOARD	1
.... 20	CB10	190 374 CIRCUIT BREAKER, auto reset 12VDC 40A	1
.....	148 850	SOCKET, relay 5 pin	2
.....	PLG4	114 062 CONNECTOR, rect univ 084 15P/S 3 row plug cable lkg	1
.....	173 916	HOUSING, contact 10-pole	1
.... 21	CB14	◆ 205 927 CIRCUIT BREAKER, auto reset 12vdc 12 amp	1
.... 22	CR1	214 876 RELAY, encl 6vdc spst 35a/14vdc 5 pin	1
.....	205 931	.. HARNESS, engine control (Deutz F3L912 engine) (consisting of)	1
.... 19	D1/C1	189 701 DIODE/CAPACITOR BOARD	1
.... 20	CB10	190 374 CIRCUIT BREAKER, auto reset 12VDC 40A	1
.....	148 850	SOCKET, relay 5 pin	2
.....	PLG4	114 062 CONNECTOR, rect univ 084 15P/S 3 row plug cable lkg	1
.... 21	CB14	205 927 CIRCUIT BREAKER, auto reset 12vdc 12 amp	1
.... 22	CR1	214 876 RELAY, encl 6vdc spst 35a/14vdc 5 pin	1
.... 23	CR8	◆ 155 309 CONTACTOR, solenoid 12VDC cont 400A inrush	1

◆ Optional

*Recommended Spare Parts.

To maintain the factory original performance of your equipment, use only Manufacturer's Suggested Replacement Parts. Model and serial number required when ordering parts from your local distributor.



802 360

Figure 15-3. Control Box Assembly – CC/CV Models

Item No.	Dia. Mkgs.	Part No.	Description	Quantity
----------	---------------	----------	-------------	----------

Figure 15-3. Control Box Assembly – CC/CV Models (Figure 15-1 Item 100)

... 1	...	F1, F2	*085 874	FUSE, mintr cer slo-blo 10A 250V	2
... 2	046 432	..	HOLDER, fuse mintr .250 x 1.250	2
... 3	201 077	..	CONTROL BOX, lh	1
... 4	201 078	..	CONTROL BOX, rh	1
... 5	201 079	..	COVER, control box	1
... 6	134 201	..	STAND-OFF, support pc card	3
... 7	PC9	192 224	CIRCUIT CARD ASSY, display	1
... 8	C9	087 110	CAPACITOR, elctlt 240uf 200VDC	1
... 9	177 136	..	CLAMP, capacitor 1.375dia	1
.....	201 495	..	HARNESS, control box, cv weld control (consisting of)	1
... 10	SR1	035 704	RECTIFIER, integ 40A 800V	1
... 11	CR5	090 104	RELAY, encl 12VDC SPST 30A/15VDC	1
.....	RC4	047 483	CONNECTOR, rect univ 084 15P/S 3 row rcpt cable/panel lkg	1
.....	RC3	158 466	CONNECTOR, rect univ 084 12P/S 3 row rcpt cable/panel lkg	1
.....	RC1	135 133	CONNECTOR, rect univ 084 9P/S 3 row rcpt cable/panel lkg	1
... 12	CB11, 12, 13	139 266	..	CIRCUIT BREAKER, man reset 1P 15A 250VAC frict	3
.....	148 850	..	SOCKET, relay 5 pin	1
.....	S6	193 324	..	SWITCH, rotary 6 position gold contacts (located on front panel, see Figure 15-5)	1
.....	S5	011 609	..	SWITCH,tgl spdt 15a 125vac on–none–on spd term chr (located on front panel, see Figure 15-5)	1
.....	150 316	..	CONN, rect univ 039 6p/s 3row plug cable lkg	6
.....	177 859	..	CONN, body 5 terminal (to engine control switch S1)	1
.....	193 183	..	CONN, rect cinch 18 pin	1

Item No.	Dia. Mkgs.	Part No.	Description	Quantity
Figure 15-3. Control Box Assembly – CC/CV Models (Continued)				
.....	196 602 PLUG, cavity 18,30 position cinch connector	4
.....	196 603 SEAL, switch 6 position rotary .250 shaft	1
.....	141 450 CONN, rect metrmate 10skt 1row plug cable lkg	1
... 13	PC7	◆ 195 706 .. MODULE, pull to idle, two output, 7 pin	1
... 14	CR4	◆ 113 247 .. RELAY, encl 12vdc dpdt 20a/120vac 8pin flange mtg	1
... 15	CR6	◆ 090104 .. RELAY, encl 12vdc spst 30a/15vdc 5pin flange mtg	1
... 16	CR2, CR3	090 104 .. RELAY, encl 12VDC SPST 30A/15VDC spin flange mtg	2
.....	206 024 HARNESS, engine control (Deutz F4L2011 engine) (consisting of)	1
... 17	R8	214 863 RESISTOR BOARD	1
... 18	CB10	190 374 CIRCUIT BREAKER, auto reset 12VDC 40A	1
.....	148 850 SOCKET, relay 5 pin	2
.....	PLG4	114 062 CONNECTOR, rect univ 084 15P/S 3 row plug cable lkg	1
.....	173 916 HOUSING, contact 10-pole	1
... 19	CR1	214 876 RELAY, encl 6vdc spst 35a/14vdc 5 pin	1
... 20	CB14	◆ 205 927 .. CIRCUIT BREAKER, auto reset 12vdc 12 amp	1
.....	205 931 HARNESS, engine control (Deutz F3L912 engine) (consisting of)	1
... 17	R8	214 863 RESISTOR BOARD	1
... 18	CB10	190 374 CIRCUIT BREAKER, auto reset 12VDC 40A	1
.....	148 850 SOCKET, relay 5 pin	2
.....	PLG4	114 062 CONNECTOR, rect univ 084 15P/S 3 row plug cable lkg	1
.....	185 655 SEAL, wire univ 15P/S 3 row	1
... 19	CR1	214 876 RELAY, encl 6vdc spst 35a/14vdc 5 pin	1
... 20	CB14	205 927 CIRCUIT BREAKER, auto reset 12vdc 12 amp	1
... 21	CR8	◆ 155 309 .. CONTACTOR, solenoid 12VDC cont 400A inrush	1

◆ Optional

*Recommended Spare Parts.


To maintain the factory original performance of your equipment, use only Manufacturer's Suggested Replacement Parts. Model and serial number required when ordering parts from your local distributor.

Notes

MATERIAL THICKNESS REFERENCE CHART

_____	24 Gauge (.025 in)
_____	22 Gauge (.031 in)
_____	20 Gauge (.037 in)
_____	18 Gauge (.050 in)
_____	16 Gauge (.063 in)
_____	14 Gauge (.078 in)
_____	1/8 in (.125 in)
_____	3/16 in (.188 in)
_____	1/4 in (.25 in)
_____	5/16 in (.313 in)
_____	3/8 in (.375 in)
_____	1/2 in (.5 in)

Hardware is common and
not available unless listed.



802 266-D

Figure 15-4. Panel, Front w/Components – CC Models

Item No.	Dia. Mkgs.	Part No.	Description	Quantity
----------	---------------	----------	-------------	----------

Figure 15-4. Panel, Front w/Components – CC Models (Figure 15-1 Item 106)

... 1	202 705 ..	PLATE SCREENED, ident control rating; when ordering this item, the nameplate should also be ordered)	1
... 2	NAMEPLATE,	screened (order by model and serial number)	1
... 3	201 580 ..	PANEL, engine/weld control	1
... 3	◆202 642 ..	PANEL, engine/weld control ss	1
... 4	S3 .. 189 382 ..	SWITCH, range/changeover	1
.....	202 223 ..	BUS BAR, idealized	2

Item No.	Dia. Mkgs.	Part No.	Description	Quantity
Figure 15-4. Panel, Front w/Components – CC Models (Continued)				
		192 558 ..	HARNESS, range (consisting of)	1
	RC6 ..	148 439 ..	HOUSING, rect univ 084 4p/s 1 row rcpt	1
... 5 ..	R1 ..	188 635 ..	RHEOSTAT, WW 300W 34 ohm	1
... 6 ..	202 209 ..	SPACER, nylon	3	
... 7 ..	S6 ..	011 622 ..	SWITCH, tgl DPDT 15A 125VAC (included in control box harness, see Figure 15-2)	1
... 8 ..	S5 ..	011 609 ..	SWITCH, tgl SPDT 15A 125VAC on-none-on spd term chr (included in control box harness, see Figure 15-2)	1
... 9 ..	RC13 ..	032 897 ..	RECEPTACLE, twlk grd 2P3W 15A 125V	1
		201 045 ..	COVER, receptacle twistlock (for RC13 (European Receptacle))	1
... 10 ..	S1 ..	176 606 ..	SWITCH, ignition 4posn w/o handle	1
... 11 ..	S2 ..	◆021 467 ..	SWITCH, tgl spst 3a 250v off–none–(on) spd term	1
... 12 ..	MS1 ..	189 698 ..	SWITCH, magnetic manual reset low current	1
		201 553 ..	CLIP, circuit breaker retaining	1
... 13 ..	CB1 ..	201 083 ..	CIRCUIT BREAKER, man reset 2P 20 A, 250VAC (European Receptacle)1	
... 13 ..	CB1 ..	◆202 683 ..	CIRCUIT BREAKER, man reset 2p 40a 240vac screw–90 (CE Rated) ..	1
		◆197 527 ..	GUARD, circuit breaker	1
	CB2, CB3	◆201 083 ..	CIRCUIT BREAKER, man reset 2p 20a 250vac	2
		201 109 ..	HARNESS, generator power (consisting of)	1
... 14 ..	CB2 ..	093 996 ..	CIRCUIT BREAKER, man reset 1P 20A 250VAC frict	3
... 15 ..	GFCI1 ..	151 981 ..	RECEPTACLE, str dx grd 2P3W 15/20A 125V GFCI	1
... 16 ..	RC1 ..	147 632 ..	RECEPTACLE, tw lk grd 2P3W 30A 250V L6-30R	1
		◆201 053 ..	HARNESS, generator power (European Receptacle) (consisting of)	1
... 14 ..	CB2 ..	◆093 996 ..	CIRCUIT BREAKER, man reset 1P 20A 250VAC frict	1
... 14 ..	CB3 ..	◆139 266 ..	CIRCUIT BREAKER, man reset 1P 15A 250VAC	1
... 15 ..	GFCI1 ..	◆151 981 ..	RECEPTACLE, str dx grd 2P3W 15/20A 125V GFCI	1
		◆213 577 ..	HARNESS, generator power (CE Rated)	1
		◆189 549 ..	BLOCK, term assy standard	1
		◆038 620 ..	LINK, jumper term block	1
... 16 ..	RC1 ..	◆176 355 ..	RECEPTACLE, str 2p3w 16a 220v flange mtg (European Receptacle) ..	1
... 16 ..	RC1 ..	◆173 556 ..	RECEPTACLE, str 2p3w 32a 130v flange mtg (CE Rated)	1
	RC2 ..	◆176 355 ..	RECEPTACLE, str 2p3w 16a 220v flange mtg (CE Rated)	1
	RC3 ..	◆173 555 ..	RECEPTACLE, str 2p3w 16a 130v flange mtg (CE Rated)	1
... 17 ..		190 861 ..	LABEL, warning electric shock and moving parts	1
... 17 ..		200 910 ..	LABEL, warning, electric shock and moving parts (Wordless Label)	1
... 18 ..		+201 106 ..	PANEL, gen pwr	1
... 18 ..		◆+202 641 ..	PANEL, gen pwr ss	1
... 18 ..		◆+201 052 ..	PANEL, gen pwr (European Receptacle)	1
... 18 ..		◆+204 258 ..	PANEL, gen pwr (110/220 volt receptacles) (CE Rated)	1
... 18 ..		◆+210 750 ..	PANEL, gen pwr ss (European Receptacle)	1
... 19 ..		083 030 ..	STUD, brs .250–20 x 1.750 w/hex collar	1
... 20 ..		601 836 ..	NUT, 250–20 .50hex .19h brs	3
... 21 ..		◆196 073 ..	LABEL, do not switch while welding	1
... 22 ..	S12 ..	◆195 825 ..	SWITCH, polarity	1
... 23 ..		201 125 ..	PANEL, mtg terminal pwr output	1
... 23 ..		◆199 303 ..	PANEL, mtg terminal pwr output ss	1
... 24 ..		039 046 ..	TERMINAL, pwr output black	1
		180 735 ..	WASHER, output stud	2
... 25 ..		181 169 ..	SPACER, output stud	2
... 26 ..		186 621 ..	BOOT, generic output stud	2
... 27 ..		◆059 773 ..	HANDLE, switch	1
... 28 ..		◆010 647 ..	PIN, spring cs .156 x 1.250	1
... 29 ..		039 047 ..	TERMINAL, pwr output red	1
... 30 ..		193 260 ..	COVER, receptacle 2.250 dia lexan	1
... 31 ..		193 258 ..	COVER, receptacle GFCI	1


Item No.	Dia. Mkgs.	Part No.	Description	Quantity
Figure 15-4. Panel, Front w/Components – CC Models (Continued)				
... 32	190 323 ..	BOOT, circuit breaker clear hex nut		1
... 33	193 143 ..	BOOT, magnetic shutdown switch		1
... 34	021 385 ..	BOOT, toggle switch lever		1
... 35	119 014 ..	LEVER, switch black		1
... 36	PL1 ..	LED, red 12V 4 ind lights panel mtg round		1
... 37	FUEL ..	GAUGE, fuel elec switch w/o sensor		1
... 38	HM ..	METER, hour 12-24VDC 2.25dia		1
... 39	189 161 ..	HANDLE, switch range		1
... 40	010 647 ..	PIN, spring CS .156 x 1.250		1
... 41	019 602 ..	KNOB, pointer		1
	024 103 ..	BLANK, snap-in nyl .750 mtg hole black		1

◆ Optional

- + When ordering a component originally displaying a precautionary label, the label should also be ordered. Order label individually or as part of Label Kit 202 031 or Label Kit 201 062 (Wordless Labels).

To maintain the factory original performance of your equipment, use only Manufacturer's Suggested Replacement Parts. Model and serial number required when ordering parts from your local distributor.


Notes



Work like a Pro!

Pros weld and cut safely. Read the safety rules at the beginning of this manual.

Hardware is common and
not available unless listed.



802 332-F

Figure 15-5. Panel, Front w/Components – CC/CV Models

Item No.	Dia. Mkgs.	Part No.	Description	Quantity
----------	---------------	----------	-------------	----------

Figure 15-5. Panel, Front w/Components – CC/CV Models (Figure 15-1 Item 106)

... 1	202 706 ..	PLATE SCREENED, ident control; when ordering this item, the nameplate should also be ordered)	1
... 2	NAMEPLATE,	screened (order by model and serial number)	1
... 3	201 580 ..	PANEL, engine/weld control	1
... 3	♦202 642 ..	PANEL, engine/weld control ss	1
... 4	S3	SWITCH, range/changeover	1
.....	♦202 223 ..	BUS BAR, idealized	2
.....	192 558 ..	HARNESS, range (consisting of)	1
.....	RC6	HOUSING, rect univ 084 4p/s 1 row rcpt	1
... 5	R1	POT, cp flat 1t 2w 1k ohm linear	1

Item No.	Dia. Mkgs.	Part No.	Description	Quantity	
Figure 15-5. Panel, Front w/Components – CC/CV Models (Continued)					
... 6	S6	193 234 ..	SWITCH, rotary 6 position gold contacts (included in control box harness, see Figure 15-3)	1	
.... 7	S5	011 609 ..	SWITCH, tgl SPDT 15A 125VAC on-none-on spd term chr (included in control box harness, see Figure 15-3)	1	
.... 8	202 209 ..		SPACER, nylon	2	
.... 9	PC6	192 995 ..	CIRCUIT CARD ASSY, connector/receptacle	1	
.... 10	CB5	139 266 ..	CIRCUIT BREAKER, man reset 1p 15a 250vac frict	1	
.... 11	S1	176 606 ..	SWITCH, ignition 4posn w/o handle	1	
.... 12	S2	021 467 ..	SWITCH, tgl spst 3a 250v off-none-(on) spd term	1	
.... 13	MS1	189 698 ..	SWITCH, magnetic manual reset low current	1	
		201 553 ..	CLIP, circuit breaker retaining	1	
.... 14	CB1	201 083 ..	CIRCUIT BREAKER, man reset 2P 20 A, 250VAC	1	
.... 14	CB1	◆202 683 ..	CIRCUIT BREAKER, man reset 2p 40a 240vac screw-90	1	
		◆197 527 ..	GUARD, circuit breaker	1	
.... CB2, CB3	◆201 083 ..		CIRCUIT BREAKER, man reset 2p 20a 250vac	2	
		201 109 ..	HARNESS, generator power (consisting of)	1	
.... 15	CB2	093 996 ..	CIRCUIT BREAKER, man reset 1P 20A 250VAC frict	1	
.... 16	GFCI1	151 981 ..	RECEPTACLE, str dx grd 2P3W 15/20A 125V GFCI	1	
.... 17	RC1	147 632 ..	RECEPTACLE, tw lk grd 2P3W 30A 250V L6-30R	1	
		◆201 053 ..	HARNESS, generator power (European Receptacle) (consisting of)	1	
.... 15	CB2	093 996 ..	CIRCUIT BREAKER, man reset 1P 20A 250VAC frict	1	
		CB3	139 266 ..	CIRCUIT BREAKER, man reset 1P 15A 250VAC	1
.... 16	GFCI1	151 981 ..	RECEPTACLE, str dx grd 2P3W 15/20A 125V GFCI	1	
		◆213 577 ..	HARNESS, generator power (CE Rated)	1	
		◆189 549 ..	BLOCK, term assy standard	1	
		◆038 620 ..	LINK, jumper term block	1	
.... 17	RC1	176 355 ..	RECEPTACLE, str 2p3w 16a 220v flange mtg (European Receptacle)	1	
.... 17	RC1	◆173 556 ..	RECEPTACLE, str 2p3w 32a 130v flange mtg (CE Rated)	1	
		RC2	◆176 355 ..	RECEPTACLE, str 2p3w 16a 220v flange mtg (CE Rated)	1
		RC3	◆173 555 ..	RECEPTACLE, str 2p3w 16a 130v flange mtg (CE Rated)	1
.... 18	RC5	◆182 954 ..	RCPT, str 3P4W 50A 125/250V	1	
.... 19		◆025 248 ..	STAND-OFF, insul .250-20 x 1.2	1	
.... 20		◆604 102 ..	CONNECTOR, clamp cable 1.000	1	
.... 21		◆197 527 ..	GUARD, circuit breaker	1	
.... 22		◆197 363 ..	TERMINAL, ring tng screw clamp	3	
.... 23	CB7	◆196 780 ..	CIRCUIT BREAKER, man reset 3p	1	
.... 24	+201 106 ..		PANEL, generator power	1	
.... 24	◆+202 641 ..		PANEL, gen pwr ss	1	
.... 24	◆+201 052 ..		PANEL, gen pwr (European Receptacle)	1	
.... 24	◆+204 258 ..		PANEL, gen pwr (110/220 volt receptacles) (CE Rated)	1	
.... 24	+◆201 107 ..		PANEL, generator power (full kVA option)	1	
.... 25	◆196 781 ..		BOOT, circuit breaker 3 pole	1	
.... 26	◆197 508 ..		PLUG, protective	1	
.... 27	◆077 440 ..		BUSHING, conduit 1 in	1	
.... 28	601 836 ..		NUT, 250-20 .50hex .19h brs	3	
.... 39	◆197 291 ..		COVER, receptacle w/gasket	1	
.... 30	083 030 ..		STUD, brs .250-20 x 1.750 w/hex collar	1	
.... CT2	◆197 433 ..		TRANSFORMER, current sensing	1	
.... 31	190 861 ..		LABEL, warning electric shock and moving parts	1	
.... 31	200 910 ..		LABEL, warning, electric shock and moving parts (Wordless Label)	1	
.... 31	◆197 399 ..		LABEL, warning 3 ph generator power	1	
.... 32	193 260 ..		COVER, receptacle 2.250 dia lexan	1	
.... 33	193 258 ..		COVER, receptacle GFCI	1	
.... 34	190 323 ..		BOOT, circuit breaker clear hex nut	1	
.... 35	S12	◆195 825 ..	SWITCH, polarity	1	
.... 36	201 125 ..		PANEL, mtg terminal pwr output	1	


Item No.	Dia. Mkgs.	Part No.	Description	Quantity
Figure 15-5. Panel, Front w/Components – CC/CV Models (Continued)				
... 37 ..	PC4, PC5 ..	189 744 ..	CIRCUIT CARD ASSEMBLY, filter hf	2
... 38 ..		039 046 ..	TERMINAL, pwr output black	1
		180 735 ..	WASHER, output stud	2
... 39 ..		134 201 ..	STAND-OFF, support	12
... 40 ..		181 169 ..	SPACER, output stud	2
... 41 ..		186 621 ..	BOOT, generic output stud	2
... 42 ..	◆	059 773 ..	HANDLE, switch	1
... 43 ..	◆	010 647 ..	PIN, spring cs .156 x 1.250	1
... 44 ..		039 047 ..	TERMINAL, pwr output red	1
... 45 ..	◆	196 073 ..	LABEL, do not switch while welding	1
... 46 ..		193 143 ..	BOOT, magnetic shutdown switch	1
... 47 ..		021 385 ..	BOOT, toggle switch lever	1
... 48 ..		119 014 ..	LEVER, switch black	1
... 49 ..		190 323 ..	BOOT, circuit breaker clear hex nut	2
... 50 ..		170 391 ..	CONN, circ ms protective cap size 20	1
... 51 ..	PL1 ..	191 241 ..	LED, red 12V 4 ind lights panel mtg round	1
... 52 ..	FUEL ..	192 265 ..	GAUGE, fuel elec switch w/o sensor	1
... 53 ..	HM ..	118 058 ..	METER, hour 12-24VDC 2.25dia	1
... 54 ..		097 922 ..	KNOB, pointer .875 dia x .250 ID w/set screws plstc	1
... 55 ..		189 161 ..	HANDLE, switch range	1
... 56 ..		010 647 ..	PIN, spring CS .156 x 1.250	1
... 57 ..		097 924 ..	KNOB, pointer 1.625 dia x .250 ID w/set scrws plstc	1
... 58 ..	CB6 ..	083 432 ..	CIRCUIT BREAKER, Man Reset 1p 10a 250vac Frict	1
		193 158 ..	HARNESS, unit weld control – CV (consisting of)	1
	PLG6 ..	114 063 ..	CONNECTOR, rect univ 084 4p/s 1 row plug cable lkg	1
	PLG8 ..	193 184 ..	CONNECTOR, rect cinch 30 pin	1
	PLG13 ..	147 992 ..	CONNECTOR, rect univ 039 10p/s 2 row plug cable	1
	PLG3 ..	158 465 ..	CONNECTOR, rect univ 084 12p/s 3 row plug cable	1
		088 731 ..	BUSHING, snap-in nyl .375 ID x .500 mtg hole	1
		135 873 ..	CLIP, conduit convoluted 1/2 in mtg hole	2
		187 654 ..	SEAL, wire univ 12p/s 3 row	1
		024 103 ..	BLANK, snap-in nyl .750 mtg hole blk	1
		120 304 ..	BLANK, snap-in nyl .250 mtg hole black	2

◆ Optional

- + When ordering a component originally displaying a precautionary label, the label should also be ordered. Order label individually or as part of Label Kit 202 031 or Label Kit 201 062 (Wordless Labels).

To maintain the factory original performance of your equipment, use only Manufacturer's Suggested Replacement Parts. Model and serial number required when ordering parts from your local distributor.

Hardware is common and not available unless listed.



802 404-C

Figure 15-6. Generator

Item No.	Dia. Mkgs.	Part No.	Description	Quantity
----------	---------------	----------	-------------	----------

Figure 15-6. Generator (Figure 15-1 Item 34)

... 1	132 053 ..	SCREW, 375-16 x 1.50hexhd pln gr 5pld	6
... 2	183 387 ..	WASHER, conical spring .406 ID x .875 OD pltd	6
... 3	195 911 ..	ENDBELL, gen (consisting of)	1
... 4	143 220 ..	O-RING, 2.859 ID x .139CS	1
... 5	201 099 ..	STATOR, exciter/gen pwr	1
... 5	♦213 448 ..	STATOR, exciter/gen pwr (CE Rated)	1
... 6	+208 287 ..	STATOR, weld assembly complete	1
... 6	+♦209 220 ..	STATOR, weld assembly complete (full kVA option)	1
... 7	013 367 ..	LABEL, warning moving parts	2
... 7	176 106 ..	LABEL, warning moving parts (Wordless Label)	2
... 8	190 197 ..	GUARD, generator wire mesh	1
... 9	172 674 ..	SPRING, ext .240 OD x .041 wire x 3.500pld	2
... 10	039 207 ..	BAFFLE, air	1
... 11	ROTOR ..	212997 .. ROTOR, Generator Segmented Assy (Includes)	1
... 12	210 446 ..	ROTOR, Generator (Includes)	1
... 13	024 617 ..	RING, Rtnq Ext 1.375 Shaft X .050 Thk	1
... 14	053 390 ..	BEARING, Ball Rdl Sgl Row 1.370 X 2.830 X .6	1
		HUB, Drive (Not Sold Separately)	1
	210 447 ..	FAN, Rotor Assy Generator (Segmented) (includes)	1
... 15	210 332 ..	PLATE, Flex Hubmount	1
... 16	206 242 ..	FAN, Rotor Segmented Assy Gen	4
... 17	049 026 ..	SCREW, M10-1.5x 25 Hex Hd-pln 8.8 Pln	10
... 18	083 883 ..	WASHER, Lock .402idx0.709odx.087t Stl Split10mm	10
... 19	080 389 ..	SCREW, 312-18x1.00 Hexwhd.66d Stl Pld Slffmg Tap-rw	8
... 20	083 883 ..	WASHER, Lock .402idx0.709odx.087t Stl Split10mm	4

Item No.	Dia. Mkgs.	Part No.	Description	Quantity
Figure 15-6. Generator (Continued)				
... 21	049 026 ..	SCREW, M10-1.5x 25 Hex Hd-pln 8.8 Pln		4
... 22	191 579 ..	COVER, starter hole Perkins/Continental		1
... 23	083 883 ..	WASHER, Lock .402idx0.709odx.087t Stl Split10mm		6
... 24	172 555 ..	SCREW, M10-1.5 x 50hexhd pln 8.8pld		6
... 25	602 159 ..	SCREW, .312-18x .75 hexwhd.66d stl pld slffmg tap-rw		6
... 26	601 961 ..	SCREW, .312-18 x 2.25hexhd pln gr 5pld		4
... 27	602 211 ..	WASHER, lock .318 ID x 0.586		6
... 28	139 341 ..	WASHER, exciter		4
... 29	*190 823 ..	BRUSH, contact		3
... 30	208 469 ..	CLIP, spring		3
... 31	189 142 ..	BRUSHHOLDER ASSEMBLY, gen		1
... 32	602 242 ..	WASHER, flat .375IDx0.875odx.083t stl pld		2
... 33	602 211 ..	WASHER, Lock .318idx0.586odx.078t Stl Pld Split.312		2
... 34	604 534 ..	SCREW, .312-18x1.25 hex hd-pln gr5 pld		2
.....	190 259 ..	HARNESS, brush (consisting of)		1
PLG1	168 071	CONNECTOR, (kit) rect univ 084 9P/S 3 row plug cable lkg		1
.....	187 651	SEAL, wire univ 9P/S 3 row		1

Figure 15-6. Generator (Continued)


- + When ordering a component originally displaying a precautionary label, the label should also be ordered. Order label individually or as part of Label Kit 202 031 or Label Kit 201 062 (Wordless Labels).

*Recommended Spare Parts.

To maintain the factory original performance of your equipment, use only Manufacturer's Suggested Replacement Parts. Model and serial number required when ordering parts from your local distributor.

Notes

Hardware is common and not available unless listed.



802 279-A

Figure 15-7. Main Rectifier Assembly

Item No.	Dia. Mkgs.	Part No.	Description	Quantity
----------	---------------	----------	-------------	----------

Figure 15-7. Main Rectifier Assembly (Figure 15-1 Item 102)

.....	SR3	201 747	RECTIFIER (consisting of)	1	
.....	SR3	◆ 203 381	RECTIFIER, environmental (consisting of)	1	
... 1	188 137 CONNECTION BOARD, rectifier AC	1	
... 2	188 517 BUS BAR, connection board	3	
... 3	188 135 ENCLOSURE, rectifier	2	
... 4	134 201 STAND-OFF, support	3	
... 5	PC3 201 449 CIRCUIT CARD ASSEMBLY, protection	1
... 6	188 136 INSULATOR, heat sink	8	
... 7	188 493 HEAT SINK, rectifier al	2	
... 8	.. D3, D5, D7	208 334 DIODE, rect 275A 300V SP	3	
... 9	.. D2, D4, D6	208 335 DIODE, rect 275A 300V RP	3	

To maintain the factory original performance of your equipment, use only Manufacturer's Suggested Replacement Parts. Model and serial number required when ordering parts from your local distributor.

TRUE BLUE®

WARRANTY

Effective January 1, 2003

(Equipment with a serial number preface of "LC" or newer)

This limited warranty supersedes all previous Miller warranties and is exclusive with no other guarantees or warranties expressed or implied.

Warranty Questions?

Call
1-800-4-A-MILLER
for your local
Miller distributor.

Your distributor also gives you ...

Service
You always get the fast, reliable response you need. Most replacement parts can be in your hands in 24 hours.

Support
Need fast answers to the tough welding questions? Contact your distributor. The expertise of the distributor and Miller is there to help you, every step of the way.

LIMITED WARRANTY – Subject to the terms and conditions below, Miller Electric Mfg. Co., Appleton, Wisconsin, warrants to its original retail purchaser that new Miller equipment sold after the effective date of this limited warranty is free of defects in material and workmanship at the time it is shipped by Miller. **THIS WARRANTY IS EXPRESSLY IN LIEU OF ALL OTHER WARRANTIES, EXPRESS OR IMPLIED, INCLUDING THE WARRANTIES OF MERCHANTABILITY AND FITNESS.**

Within the warranty periods listed below, Miller will repair or replace any warranted parts or components that fail due to such defects in material or workmanship. Miller must be notified in writing within thirty (30) days of such defect or failure, at which time Miller will provide instructions on the warranty claim procedures to be followed.

Miller shall honor warranty claims on warranted equipment listed below in the event of such a failure within the warranty time periods. All warranty time periods start on the date that the equipment was delivered to the original retail purchaser, or one year after the equipment is sent to a North American distributor or eighteen months after the equipment is sent to an International distributor.

1. 5 Years Parts — 3 Years Labor
 - * Original main power rectifiers
 - * Inverters (input and output rectifiers only)
2. 3 Years — Parts and Labor
 - * Transformer/Rectifier Power Sources
 - * Plasma Arc Cutting Power Sources
 - * Semi-Automatic and Automatic Wire Feeders
 - * Inverter Power Supplies
 - * Intellitig
 - * Maxstar 150
 - * Engine Driven Welding Generators
(NOTE: Engines are warranted separately by the engine manufacturer.)
3. 1 Year — Parts and Labor Unless Specified
 - * DS-2 Wire Feeder
 - * Motor Driven Guns (w/exception of Spoolmate Spoolguns)
 - * Process Controllers
 - * Positioners and Controllers
 - * Automatic Motion Devices
 - * RFCS Foot Controls
 - * Induction Heating Power Sources
 - * Water Coolant Systems
 - * Flowgauge and Flowmeter Regulators (No Labor)
 - * HF Units
 - * Grids
 - * Maxstar 85, 140
 - * Spot Welders
 - * Load Banks
 - * Racks
 - * Running Gear/Trailers
 - * Plasma Cutting Torches (except APT & SAF Models)
(NOTE: Field options are covered under True Blue® for the remaining warranty period of the product they are installed in, or for a minimum of one year — whichever is greater.)
 - * Field Options
4. 6 Months — Batteries
5. 90 Days — Parts
 - * MIG Guns/TIG Torches

- * Induction Heating Coils and Blankets
- * APT & SAF Model Plasma Cutting Torches
- * Remote Controls
- * Accessory Kits
- * Replacement Parts (No labor)
- * Spoolmate Spoolguns
- * Canvas Covers

Miller's True Blue® Limited Warranty shall not apply to:

1. **Consumable components; such as contact tips, cutting nozzles, contactors, brushes, slip rings, relays or parts that fail due to normal wear. (Exception: brushes, slip rings, and relays are covered on Bobcat, Trailblazer, and Legend models.)**
2. Items furnished by Miller, but manufactured by others, such as engines or trade accessories. These items are covered by the manufacturer's warranty, if any.
3. Equipment that has been modified by any party other than Miller, or equipment that has been improperly installed, improperly operated or misused based upon industry standards, or equipment which has not had reasonable and necessary maintenance, or equipment which has been used for operation outside of the specifications for the equipment.

MILLER PRODUCTS ARE INTENDED FOR PURCHASE AND USE BY COMMERCIAL/INDUSTRIAL USERS AND PERSONS TRAINED AND EXPERIENCED IN THE USE AND MAINTENANCE OF WELDING EQUIPMENT.

In the event of a warranty claim covered by this warranty, the exclusive remedies shall be, at Miller's option: (1) repair; or (2) replacement; or, where authorized in writing by Miller in appropriate cases, (3) the reasonable cost of repair or replacement at an authorized Miller service station; or (4) payment of or credit for the purchase price (less reasonable depreciation based upon actual use) upon return of the goods at customer's risk and expense. Miller's option of repair or replacement will be F.O.B., Factory at Appleton, Wisconsin, or F.O.B. at a Miller authorized service facility as determined by Miller. Therefore no compensation or reimbursement for transportation costs of any kind will be allowed.

TO THE EXTENT PERMITTED BY LAW, THE REMEDIES PROVIDED HEREIN ARE THE SOLE AND EXCLUSIVE REMEDIES. IN NO EVENT SHALL MILLER BE LIABLE FOR DIRECT, INDIRECT, SPECIAL, INCIDENTAL OR CONSEQUENTIAL DAMAGES (INCLUDING LOSS OF PROFIT), WHETHER BASED ON CONTRACT, TORT OR ANY OTHER LEGAL THEORY.

ANY EXPRESS WARRANTY NOT PROVIDED HEREIN AND ANY IMPLIED WARRANTY, GUARANTY OR REPRESENTATION AS TO PERFORMANCE, AND ANY REMEDY FOR BREACH OF CONTRACT TORT OR ANY OTHER LEGAL THEORY WHICH, BUT FOR THIS PROVISION, MIGHT ARISE BY IMPLICATION, OPERATION OF LAW, CUSTOM OF TRADE OR COURSE OF DEALING, INCLUDING ANY IMPLIED WARRANTY OF MERCHANTABILITY OR FITNESS FOR PARTICULAR PURPOSE, WITH RESPECT TO ANY AND ALL EQUIPMENT FURNISHED BY MILLER IS EXCLUDED AND DISCLAIMED BY MILLER.

Some states in the U.S.A. do not allow limitations of how long an implied warranty lasts, or the exclusion of incidental, indirect, special or consequential damages, so the above limitation or exclusion may not apply to you. This warranty provides specific legal rights, and other rights may be available, but may vary from state to state.

In Canada, legislation in some provinces provides for certain additional warranties or remedies other than as stated herein, and to the extent that they may not be waived, the limitations and exclusions set out above may not apply. This Limited Warranty provides specific legal rights, and other rights may be available, but may vary from province to province.





Owner's Record

Please complete and retain with your personal records.

Model Name	Serial/Style Number
Purchase Date	(Date which equipment was delivered to original customer.)
Distributor	
Address	
City	
State	Zip



For Service

Call 1-800-4-A-Miller or see our website at www.MillerWelds.com to locate a DISTRIBUTOR or SERVICE AGENCY near you.

Always provide Model Name and Serial/Style Number.

Contact your Distributor for:	Welding Supplies and Consumables Options and Accessories Personal Safety Equipment Service and Repair Replacement Parts Training (Schools, Videos, Books) Technical Manuals (Servicing Information and Parts) Circuit Diagrams Welding Process Handbooks
-------------------------------	--

Contact the Delivering Carrier to:	File a claim for loss or damage during shipment. For assistance in filing or settling claims, contact your distributor and/or equipment manufacturer's Transportation Department.
------------------------------------	--

Miller Electric Mfg. Co.

An Illinois Tool Works Company
1635 West Spencer Street
Appleton, WI 54914 USA

International Headquarters—USA
USA Phone: 920-735-4505 Auto-Attended
USA & Canada FAX: 920-735-4134
International FAX: 920-735-4125

European Headquarters – United Kingdom
Phone: 44 (0) 1204-593493
FAX: 44 (0) 1204-598066

www.MillerWelds.com